

3. Status of Release of EMD of Unsuccessful Tenderers

Status of Release of EMD of Unsuccessful tenderers (Position up to 31.01.2011)							
Sr. No.	Name of Work	NIT NO.	Name of Unsucessful Tenderes	Dt. Of Finalisation of Tender	Dt. Of letter sent to Finance for release	Dt. Of Release of EMD	Remarks
1	Carrying out following four miscellaneous works under Assistant Divisional Engineer (HQ) Jabalpur. 1) Repairs to goods platform of Kachhpura goods shed BRGT End). 2.) Repairs to boundary wall of Kachhpura goods shed between private land and Railway land. 3.) Repairs to leaning platform walling of platform No. 1 at Madan Mahal station (KEQ End) 4.) Repairs to existing front boundary wall of Howbagh (Nehru Colony) Jabalpur.	103/2010	1. Ckendra Aftab BPL 2. Choudhary Associate JBP 3. Shri Vidya Nand Tiwari JBP 4. Shri Pradeep Kumar Wadhvani JBP 5. M/s Rajeev Enterprises JBP 6. Preet Construction Co. JBP	19.01.2011	19.01.2011		
2	Repairs to Leaky roof in staff quarters at Kaima, Hinota, Rewa, Tikariya, Markundi, Baramafi, and Satna station under ADEN STA sub division.	109/2010	1. Shri R.K. Jaiswal Rewa 2. Shri Madadgiri Const. 3. Shri M.K. Singh Satna 4. Rambadan Pandey Satna 5. M/s R.K. Dwivedi Satna 6. Maheshwari Water Proffing BPL 7. Maheshwari Water Proofing BPL 8. M/s Shailendra Singh STA 9. M/s P.D. Kuchaya Satna	16.01.2011	18.01.2011		
3	Deep screening by BCM and manually at obligatory points on Dn road from Kms. 1028.00 to 1053.00 =25.00 Km Dn. 1028.00 to 1029.80 = 1.80 Up, 1098.40 to 1107.45 = 9.05 Km Up, 1169.00 to 1178.00 = 9.00 Km Up, 1214.90 to 4.00 Km up and 1233.30 to 1239.30 =6.00 Km up Total 54.85 Kms under Sr. Divisinal Engineer (North) on Jabalpur-Manikpur section.	93/10	Shri R.L. Chaurasia	16.01.2011	18.01.2011		

3. Status of Release of EMD of Unsuccessful Tenderers

4	03 misc works under Divisional Engineer Satna sub division. 1.)Repair to station approach road with asphaltting at Satna. 2) Repair to Colony road at Satna by cement concrete road. 3) Provision of WBM road from L.C. no. 401 to 402.	114/10	1. M/s Vindhya Construction Co. 2. Shri Vidyanand Tiwari JBP 3. Shri Kamadgiri Const. 4. M/s S.N. Pandey Const. 5. M/s Raja Const. Co.	17.01.2011	18.01.2011		
5	Replacement of defcective weld of 52 Kg/60 Kg. 90 UTS rails, using 75 mm AT weld at various locations on ET-SHR section under Divisional Engineer (S) JBP section.	62/10	M/s India Thermit Corporation Ltd. Kanpur	31.01.10	02.02.2011		