

Annexure to PAC against PL No 25718393

COS file No. 20.15.3569 (15)

SCHNEIDER ELECTRIC INFRASTRUCTURE LIMITED MAKE IOH REPLACEMENT KIT FOR SINGLE BOTTLE
VCB TYPE 22CB CODE NO. 5510750

SR. NO	PART NO.	DESCRIPTION	QTY IN SET	DATE OF SUPPLY	CLARIFICATION/ DEVIATIONS
	5510750	IOH REPLACEMENT KIT CONSIST OF :			
A	5510740	AOH REPLACEMENT KIT COSISTING OF :	1 Kit		
1	5260700	- O RING FOR MAGNET VALVE ASSEMBLY	3 Nos		
2	5260800	- O RING FOR MAGNET VALVE ASSEMBLY	2 Nos		
3	5260600	- VALVE (FLUTED) FOR MAGNET VALVE	2 Nos		
4	5570080	- O RING FOR RELAY VALVE & REDUCER	2 Nos		
5	5570090	- O RING FOR RELAY VALVE ASSEMBLY	1 No		
6	5570100	- O RING FOR RELAY VALVE ASSEMBLY	1 No		
7	5570110	- O RING FOR RELAY VALVE ASSEMBLY	1 No		
8	5150020	- PTFE VALVE DISCS FOR RELAY VALVE	2 Nos		
9	5540060	- SPECIAL WASHER FOR MAIN PISTON	1 No		
10	5510163	- SEALING WASHER FOR BOTTOM COVER	8 Nos		
	5510164	- RETAINING RING FOR BOTTOM COVER	8 Nos		
	5110600	- REPAIR KIT FOR AIR FILTER CONSISTING OF	1 Kit		
		a) 'O' RING - 1 No			
		b) GASKET - 2 Nos.			
		c) STUD - 1 No.			
13	5110422	REPAIR KIT FOR PRESSURE REGULATOR CONSISTING OF ONE NO EACH, DIAPHRAGM ASSEMBLY, SLIP RING, VALVE, VALVE SEAT, GASKET SEAT & VALVE SPRING	1 Kit		
14	5510980	WASHER FOR BANJO COUPLING	8 Nos.		
15	5290040	PVC CHANNEL FOR GIMOTA CONN. PLATE	0.3 Mtrs.		
B		BALANCE IOH KIT :			
16	5380650	GROMMET FOR BASE PLATE	1 No		
17	5510390	'O' RING (BETWEEN FLANGE)	1 No		
18	5510450	SELON WASHER (FOR PLUG OF CYLINDER)	1 No		
19	5510810	GASKET FOR BASE PLATE	1 No		
20	5510162	SEALING STRIP FOR BOTTOM COVER	2.3 Mt		
21	5540030	DAMPER ASSEMBLY FOR CYLINDER	1 No.		
22	5570050	PISTON SEAL RING FOR RELAY VALVE PISTON	1 No.		
23	5540023	PISTON SEAL RING FOR MAIN PISTON	1 No.		
24	5510490	FILTER ELEMENT	1 No.		
25	5390100	MOLECULAR SIEVES FOR AIR DRYER	4 kg		
26	5350000	SURGE SUPPRESSOR FOR MAGNET VALVE ASSEMBLY	1 No.		
27	5150010	POPPET VALVE FOR RELAY VALVE	1 No.		
28	5203400	AUXILIARY CONTACT UNIT (8-WAY)	1 No.		
		REPAIR KIT :			

The Code No. of Sr. No. (13), (25) and (26) in RDSO SMI, was erroneously mentioned as 5510730, 5390090, 5350100. The correct Code No. as per Schneider price list is 5110422, 5390100, 5350000. Please therefore issue the annexure as per our offer.

For TRINITY HOUSE (INDIA) PVT. LTD.

Authorized Signatory

AEEE/KCO/HQ/WCR