

उप मुख्य सामग्री प्रबंधक कार्यालय  
Dy. CMM/CRWS/BHOPAL

No. 68.13-WB- 02

Date ; 21.05.2013

Tender to be closed on... **04.06.2013**..... at 14:30 Hrs .

सुपुर्दगी का स्थान : उप मुख्य सामग्री प्रबंधक,सडिपुका,मेन स्टोर,भोपाल  
Place Of Delivery : Dy. CMM (CRWS) BPL {AT MAIN STORES}  
सुपुर्दगी अवधि : ३० दिन ६ भंडार उपलब्धता के अनुसार  
Delivery Terms : 30 Days / Ex stock

Sr.No	Tender No	Description	Qty
1.	68.13.5341	Set of Lavatory door arrangement (for AC Coaches ) to Drg.No. ICF/STD-5-6-011 alt'u' Col-II &VI in assembled condition. Note:item No. 2 to be sourced from the RDSO approved source only and the colour,shade and pattern of panels shall be as per RDSO/SK/514 Sample code No. AC-SP02.as per Drg.No. ICF/STD-5-6-011 alt'u' Col-I &VI.	10 Sets
2.	68.13.5342	Set of Lavatory door arrangement (for AC Coaches ) to Drg.No. ICF/STD-5-6-011 alt'u' Col-I &V in assembled condition. Note:item No. 2 to be sourced from the RDSO approved source only and the colour,shade and pattern of panels shall be as per RDSO/SK/514 Sample code No. AC-SP02.as per Drg.No. ICF/STD-5-6-011 alt'u' Col- I &V.	10 Sets
3	68.13.5343	Alarm Pull Handle Complete for CZCoaches. AS per Drg.No.CRW/SK-725 Alt.2 Item No.1,2,3,6,9 &10 in assembled condition.	1200 Nos
4	68.13.5345	High Performanec Anti-corrosion Epoxy Coating (Tow Pack) red brown colour as per RDSO spece no. M&C/pcn/123-6 packing in 20 liter. New Non- returnable M.S.Drum.	220 Ltrs
5	68.13.5346	Laminated Safety plain glass for Comunication door of AC Coaches.Size:-895X432X5MM thick to IS:2553 Part -I.	150 Nos
6	68.13.5347	Cable Box to Drg. No. Wlc2-7-1-202.Col-I,Alt-'K'	50 Nos
7	68.13.5348	Box Complete (Battery fuse and EFT) to Drg. No. GS-7-1-022/Col-II Alt.'h' fitted with battery ,fuse arrangement to Drg.No. WFC2-7-1-207/Col-I Alt-F without crimping socket of item No.4 with copper bussmann/Havells make fuse.	50 Nos
8	68.13.5349	Bracket for Lower Spring Beam As per drawing No. WLRRM-0-5-002 Alt.'y' & 4 Item 4& 5 in assembled condition 50% LH 50%RH.	400 Nos
9	68.12.5350	Bulb type split cotter for Buffer spindle,size 04x20x76mm. Specification:M-41-74 or IS:1079-73 St.42..Drg.No. RDSO Drg.No. WD94068-S-1 alt.4,item.2.	2600 Nos
10	68.13.5351	Support Plate for P.E.A.S.V.to Drg.No.CRWS/SK/AB-49.	650 Nos
11	68.13.5352	Traverser Rail Skid for Shunting Drg.No. CRWS/SK/793.ITEM No. 4,Thewidth and partial Length of	32 Nos

		Tongue should be 100mm & 250mm instead of 65mm & 190 mm respectively-Item No.5, The inner size and outer size of channel should be 105mm & 125mm instead of 70mm & 90mm respectively.	
12	68.13.5353	M-12 Spring washer (Bright Zinc Plated) IS:3063 Standard item.	85650 Nos
13	68.13.5354	Alarm Signal Disc, as per Drg.No. VB-129/M.	1300 Nos
14	68.13.5245	Set of Bihexagonal Socket ½ inches square drive flank drive (H) Exel socket's (G) Socket's As per Annexure 'D' & 'E' (Taparia Design No or Equivalent) Make- Taparia, Jhalani, Hira, Everest (At the time of supply proof of purchased from OEM Authorized Dealer must be submitted) Annexure 'D'-10 item=65 nos, Annexure E=1 item=20 Nos. (Annexure D+E=11 times=85 Nos).	01 Set
15	68.13.5299	Chair Angle complete (Transverse side) as per AE-61373, Alt-b'	200 Nos
16	68.13.5290	Spring washer M-8 Steel to IS:3063 bright zinc plated to be supplied in 100 Nos packing. (01 UNIT=100 Nos.)	800 Unit
17	68.13.5296	P.K. Screw Slotted Raised head size-10x75mm	50 units
18	68.13.5153	Set of 'T' type straight curtain bracket chromium plated size-20mm dia (3/4").. One set consisting of (1) Socket 20 mm dia=02 Nos. (2) Base=02 No=Total quantity in one set=04 Nos in assembled condition as IS:1079.	200 Set
19	68.13.5270	Eye for pad Lock for B.S. Door of ICF & BEML Coaches As per Drg.No. CRW/SK-415, Item No. 3 to IS:1079.	2000 Nos
20	68.13.5360	Frame for transverse upper middle & Lower berth for CN Coaches. As per Drg.No. SE-61318.alt.'a'	54 Nos
21	68.13.5361	Frame for Longitudinal upper berth for CN Coaches. As per Drg. No. SE-61320.alt.'a'	27 Nos
22	68.13.5362	Bearing Complete for berth frame. As per Drg.No. AE-61271.alt.'e'	540 Nos
23	68.13.5304	Expanded metal partition frame Below single seat for GS Coaches -Col-II, Drg.No. T4-3-803, Alt.-7 & E.	550 Nos
24	68.13.5344	Modified Belt Tensioning Bracket. (Stopper for Rotaring) as per Drg. No. T-O-3-678 Alt. g; item 5 & 6 (in assembled condition).	800 Nos

Dy.CMM/CRWS/BPL

Fax No. 0755-2743643, 2747414,  
Email ID: [dycmm.pps@gmail.com](mailto:dycmm.pps@gmail.com)