

3815.5005

hit
RU

2A

INDENT No. BR/STORE/91513037 dt. 16/10/15 ANNEXTURE "A"

S.NO.	DESCRIPTION OF ITEMS	DRAWING NO.	ITEM NO.	QTY./SET	QTY. FOR 800 SETS	UNIT
1	SLIDING DOOR-L.H. (IN ASSEMBLED CONDITION)	WD-11043-S-01,ALT-01 OR LATEST	1,3,5,6,8,9,10,12,13,14, 15,16, 17,,22,29,30,	1	800	NOS.
2	SLIDING DOOR-R.H. (IN ASSEMBLED CONDITION)	WD-11043-S-01,ALT-01 OR LATEST	2,3,5,6,8,9,10,12,13,14, 15,16,17,,22,29,30,	1	800	NOS.
3	SLIDER CHANNEL ASSEMBLY		4	2	1600	NOS.
4	HORIZONTAL ROLLER		7	4	3200	NOS.
5	GUIDE RAIL ASSEMBLY		18,19,23,31	2	1600	NOS.
6	BARRAL BOLT HOLD BKT.		24	2	1600	NOS.
7	RAIN COVER PLATE AT BOTTOM(L.H.)		26	1	800	NOS.
8	RAIN COVER PLATE AT BOTTOM(R.H.)		27	1	800	NOS.
9	SUPPORTING PLATE FOR ANGLE AT DOOR		28	8	6400	NOS.
10	STIFFENING PLATE		8	4	3200	NOS.
11	END COVER PLATE		9	2	1600	NOS.
12	STIFFENING PLATE		10	1	800	NOS.
13	WATER PROTECTION STRIP		17	1	800	NOS.
NOTE -FOR S.NO. 1,2,3						
S. NO. 1	SLIDING DOOR-L.H.	ONE SET CONSISTS OF MATING PART L.H. & R.H. SLIDING DOOR SHOULD BE FREE FROM WARPING				
S. NO. 2	SLIDING DOOR-R.H.					
S. NO. 3	SLIDER CHANNEL ASSEMBLY	INTERNAL SURFACE OF SLIDER CHANNEL SHOULD BE FREE FROM SPATTERS & FOREIGN PARTICLES FOR SMOOTH RUNNING OF ROLLERS				

Signature
 St. Sec. Engineer (B. R. Shop)
 Wagon Repair Shop (W.C.R.) KOTA

Signature of Controlling officer
 WRS (W.C.R.) KOTA

29

5