

Office of the DyCE(TM)/BPL
TENDER UNDER FINALISATION (Dy.CE/TM/BPL)

March , 16											
S.N.	Name of work	NIT No.	Value of tender in Rs.	Stage of Tender						Remark	File NO,
				Briefing note and comparative statement	Vetting of Briefing Note	Tender Committee minutes finalised	Tender Committee minutes acceptance	Acceptance letter issued			
				Yes/No	Yes/No	Yes/No	Yes/No	Yes/No			
1	Cooling unit (hydraulic oil collar) required for BCM machine working in WCR	BPL/W/TM/2015-16/18/38 dtd.17.12.15	623685	Yes	Yes	No	No	No	TC to be done	14/172	
2	Shock absorber required for BRM -101 machine	BPL/W/TM/2015-16/18/38 dtd.17.12.15	246013	Yes	Yes	No	No	No	TC to be done	15/0081	
3	Repairing of wheel axle frame of DUO-8042 M/C	BPL/W/TM/2015-16/17/37 dtd.30.11.15	98500	Yes	Yes	No	No	No	TC to be done	15/229	
4	Painting of FRM-1892 & BRM-101 track machine	BPL/W/TM/2015-16/17/37 dtd.30.11.15	94910	Yes	Yes	No	No	No	TC to be done	15/251	
5	Overhauling & repairing of control panel box of BCM 319 machine at ZTMD BPL	BPL/W/TM/2015-16/17/37 dtd.30.11.15	64900	Yes	Yes	No	No	No	TC to be done	15/153	
6	Wheel cylinder required for T-28 track machine.	BPL/W/TM/2015-16/19/39 dtd. 17.12.15	154000	Yes	Yes	No	No	No	TC to be done	15/0058	
7	Phosphor bronze plate required for T-28 machines.	BPL/W/TM/2015-16/19/39 dtd. 17.12.15	120960	Yes	Yes	No	No	No	TC to be done	15/0221	
8	Fastener required for track machines.	BPL/W/TM/2015-16/19/39 dtd. 17.12.15	127530	Yes	Yes	No	No	No	TC to be done	15/0205	
9	Brake shoe required for track machine.	BPL/W/TM/2015-16/19/39 dtd. 17.12.15	119700	Yes	Yes	No	No	No	TC to be done	15/0206	
10	Switch required for track machine.	BPL/W/TM/2015-16/19/39 dtd. 17.12.15	138474	Yes	Yes	No	No	No	TC to be done	15/0208	
11	Lifting roller required for track machine.	BPL/W/TM/2015-16/19/39 dtd. 17.12.15	140680	Yes	Yes	No	No	No	TC to be done	15/0231	

12	Overhauling /Major attention of ATRT P811S machine in ZTMD/BPL	BPL/W/TM/2015-16/22/42 dtd.08.01.16	15166085	Yes	Yes	No	No	No	TC to be done	ATRT/1
13	Trolley wheel required for track machines.	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	123027	Yes	Yes	No	No	No	TC to be done	15/0233
14	Lifting hook required for UNIMAT machines.	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	139991	Yes	Yes	No	No	No	TC to be done	15/0232
15	Valve required for Plassermatic machines working in WCR.	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	224148	Yes	Yes	No	No	No	TC to be done	14/0149
16	Spares required for repairing of drive pump for BCM machine.	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	299550	Yes	Yes	No	No	No	TC to be done	15/0057
17	Wheel support cylinder required for T-28 machines	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	119920	Yes	Yes	No	No	No	TC to be done	15/204
18	Accumulator required for track machine. Make:- HYDAC/Plasser or equivalent	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	95389	Yes	Yes	No	No	No	TC to be done	15/279
19	Cutting chain assembly with carbide bit required for BCM Machines.	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	4260060	Yes	Yes	No	No	No	TC to be done	15/0101
20	Pinion shaft required for clutch assembly of BCM machines working in	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	773526	Yes	Yes	No	No	No	TC to be done	14/0151
21	Hydraulic hoses required for unimat machines.	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	72240	Yes	Yes	No	No	No	TC to be done	15/0282
22	Spares and rewiring of drive control panel box of B-5 & Junction box B-50 with testing and commissioning for CSM-924 m/c at ZTMD Bhopal	BPL/W/TM/2015-16/21/41 dtd. 30.12.15	143938	Yes	Yes	No	No	No	TC to be done	Rewiring CSM-924