

**Office of the DyCE(TM )/BPL**  
**TENDER UNDER FINALISATION (Dy.CE/TM/BPL)**

June , 2016											
S.N.	Name of work	NIT No.	Value of tender in Rs.	Stage of Tender						Remark	File NO,
				Briefing note and comparative statement	Vetting of Briefing Note	Tender Committee minutes finalised	Tender Committee minutes acceptance	Acceptance letter issued			
				Yes/No	Yes/No	Yes/No	Yes/No	Yes/No			
1	Cardon shaft required for track machine.Part No.KGV180.1250.110.80. Make:- Plasser or equivalent.	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	135842/-	Yes	Yes	No	No	No	negotiation fixed on 11.07.16	15/289	
2	Double Pump required for track machine. Make:- VELJON DENISON	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	135842/-	Yes	Yes	No	No	No	negotiation fixed on 11.07.16	15/291	
3	Transmission oil SAE-30 required for UTV machines. Make:- IOCL,BPCL,HPCL	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	138474/-	Yes	Yes	No	No	No	Under vetting cost more than 1.5 lakh	15/305	
4	Spares required for repairing of fuel Injection Pump	15-16/186/179 dtd.28.03.16	41796	Yes	Yes	No	No	No	TC to be done	15/0364	
5	Spares required for repairing of self starter and alternator .	15-16/185/178 dtd. 28.03.16	74530	Yes	Yes	No	No	No	TC to be done	15/0357	
6	Spares required for repairing of cummins Engine NTA-855 to Duo-8081 Machine	15-16/184/177 dtd. 28.03.16	47257	Yes	Yes	No	No	No	TC to be done	15/0362	
7	Special head bolt with nut and washer required for BCM machine.Part No. Bolt-61.04.218/nut M-10DIN984-8/SPRING- B10DIN934.8. Make:- Plasser or equivalent.	BPL/W/2015-16/24/44 dtd. 18.03.16	86940/-	Yes	Yes	No	No	No	TC to be done	15/313	
8	Outer rewiring of BRM-101 machine during IOH.Make:- Plasser or equivalent.	BPL/W/2015-16/24/44 dtd. 18.03.16	141439	Yes	Yes	No	No	No	TC to be done	15/315	

9	Bench vice required for track machine. Make :-Gedore,Ajay, Ambika or equivalent.	BPL/W/2015-16/24/44 dtd. 18.03.16	99180/-	Yes	Yes	No	No	No	TC to be done	15/324
10	Spares required for track machine. Make :-Veljan Denison	BPL/W/2015-16/24/44 dtd. 18.03.16	145327/-	Yes	Yes	No	No	No	TC to be done	15/327
11	Valve & pneumatic cylinder required for unimat 8268, unimat-8301, DGS-334 machine during IOH.Make :-Plasser or Equivalent.	BPL/W/2015-16/24/44 dtd. 18.03.16	137876/-	Yes	Yes	No	No	No	TC to be done	15/328
12	Hydraulic Suction hose required for track machine. Hyd Hose, Internal Dia-4" Make:-Superseal, Parker	BPL/W/2015-16/24/44 dtd. 18.03.16	86940/-	Yes	Yes	No	No	No	TC to be done	15/329
13	Tie drop pad required for ATRT machine.Part no. B0022Y01Make :-Harsco or Equivalent	BPL/W/2015-16/24/44 dtd. 18.03.16	70350/-	Yes	Yes	No	No	No	TC to be done	15/330
14	Motor Starting required for Cummins KTA1150L Engines of track machine. Make:- Cummins or equivalent.Part No.4906788/4912939	BPL/W/TM/2015-16/25/45 dtd.21.03.16	147600	Yes	Yes	No	No	No	TC to be done	15/350
15	Ratechet lifting and traversing jack required for track machines. Capacity 50 Tones. Make:- BEST,HY-TRACK MAMCO	BPL/W/TM/2015-16/25/45 dtd.21.03.16	184800	Yes	Yes	No	No	No	TC to be done	15/103
16	Lifting and traversing Ratechet jack required for track machines. Capacity 25 Tones. Make:- BEST,HY-TRACK MAMCO	BPL/W/TM/2015-16/25/45 dtd.21.03.16	184500	Yes	Yes	No	No	No	TC to be done	15/102
17	Clutch gear wheel required for pinion shaft assembly of BCM machine working in WCR	BPL/W/TM/2015-16/25/45 dtd.21.03.16	645209	Yes	Yes	No	No	No	TC to be done	14/170
18	Wear plate required for BCM Machines. Make:- INDIGENOUS	BPL/W/TM/2015-16/25/45 dtd.21.03.16	165200	Yes	Yes	No	No	No	TC to be done	15/0098
19	Vertical lift cylinder required for T-28 machines. Part No. 0017018 C. Make:-AMECA or equivalent.	BPL/W/TM/2015-16/25/45 dtd.21.03.16	173513	Yes	Yes	No	No	No	TC to be done	15/0096
20	Hydraulic hoses required for track machines during IOH. Make:-PARKER,SUPERSEAL, AEROQUIP	BPL/W/TM/2015-16/25/45 dtd.21.03.16	113843	Yes	Yes	No	No	No	TC to be done	15/311
21	Hydraulic Cylinder ( Main Boom) required for UTV Machines. Part N. 2P28. Make:- Phooltas or equivalent.	BPL/W/TM/2015-16/25/45 dtd.21.03.16	171675	Yes	Yes	No	No	No	TC to be done	15/121

22	Stablizer required for BRM-101 during IOH of machine. Part No. 195258. Make:-KERSHAW or equivalent.	BPL/W/TM/2015-16/25/45 dtd.21.03.16	450300	Yes	Yes	No	No	No	TC to be done	15/0097
23	Cardon Shaft required for track machine. Part No. KGV180.1550.110.80. Make:-Plasser or equivalent.	BPL/W/TM/2015-16/25/45 dtd.21.03.16	111825	Yes	Yes	No	No	No	TC to be done	15/352
24	Induction heater required for track machine. Capacity 4 KVA. Make:-UNITECH or equivalent.	BPL/W/TM/2015-16/25/45 dtd.21.03.16	79925	Yes	Yes	No	No	No	TC to be done	15/351
25	Wear plate required for BCM machines. Make:- INDIGENOUS	BPL/W/TM/2015-16/25/45 dtd.21.03.16	163234	Yes	Yes	No	No	No	TC to be done	15/107