

Office of the DyCE(TM)/BPL
TENDER UNDER FINALISATION (Dy.CE/TM/BPL)

August , 2016									
S.N.	Name of work	NIT No.	Value of tender in Rs.	Stage of Tender					
				Briefing note and comparative statement	Vetting of Briefing Note	Tender Committee minutes finalised	Tender Committee minutes acceptance	Acceptance letter issued	Remark
				Yes/No	Yes/No	Yes/No	Yes/No	Yes/No	
1	Cardon shaft required for track machine.Part No.KGV180.1250.110.80. Make:- Plasser or equivalent.	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	94500/-	Yes	Yes	No	No	No	TC to be done
2	Double Pump required for track machine. Make:- VELJON DENISON	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	135842/-	Yes	Yes	No	No	No	TC to be done
3	Outer rewiring of BRM-101 machine during IOH.Make:- Plasser or equivalent.	BPL/W/2015-16/24/44 dtd. 18.03.16	141439	Yes	Yes	No	No	No	TC to be done
4	Motor Starting required for Cummins KTA1150L Engines of track machine. Make:- Cummins or equivalent.Part No.4906788/4912939	BPL/W/TM/2015-16/25/45 dtd.21.03.16	147600	Yes	Yes	No	No	No	TC to be done
5	Ratechet lifting and traversing jack required for track machines. Capacity 50 Tones. Make:- BEST,HY-TRACK MAMCO	BPL/W/TM/2015-16/25/45 dtd.21.03.16	184800	Yes	Yes	No	No	No	TC to be done
6	Lifting and traversing Ratechet jack required for track machines. Capacity 25 Tones. Make:- BEST,HY-TRACK MAMCO	BPL/W/TM/2015-16/25/45 dtd.21.03.16	184500	Yes	Yes	No	No	No	TC to be done
7	Clutch gear wheel required for pinion shaft assembly of BCM machine working in WCR	BPL/W/TM/2015-16/25/45 dtd.21.03.16	645209	Yes	Yes	No	No	No	TC to be done

Office of the DyCE(TM)/BPL
TENDER UNDER FINALISATION (Dy.CE/TM/BPL)

August , 2016									
S.N.	Name of work	NIT No.	Value of tender in Rs.	Stage of Tender					
				Briefing note and comparative statement	Vetting of Briefing Note	Tender Committee minutes finalised	Tender Committee minutes acceptance	Acceptance letter issued	Remark
				Yes/No	Yes/No	Yes/No	Yes/No	Yes/No	
8	Wear plate required for BCM Machines. Make:- INDIGENOUS	BPL/W/TM/2015-16/25/45 dtd.21.03.16	165200	Yes	Yes	No	No	No	TC to be done
9	Vertical lift cylinder required for T-28 machines. Part No. 0017018 C. Make:-AMECA or equivalent.	BPL/W/TM/2015-16/25/45 dtd.21.03.16	173513	Yes	Yes	No	No	No	TC to be done
10	Hydraulic hoses required for track machines during IOH. Make:-PARKER,SUPERSEAL, AEROQUIP	BPL/W/TM/2015-16/25/45 dtd.21.03.16	113843	Yes	Yes	No	No	No	TC to be done
11	Hydraulic Cylinder (Main Boom) required for UTV Machines. Part N. 2P28. Make:- Phooltas or equivalent.	BPL/W/TM/2015-16/25/45 dtd.21.03.16	171675	Yes	Yes	No	No	No	TC to be done
12	Stablizer required for BRM-101 during IOH of machine. Part No. 195258. Make:-KERSHAW or equivalent.	BPL/W/TM/2015-16/25/45 dtd.21.03.16	450300	Yes	Yes	No	No	No	TC to be done
13	Cardon Shaft required for track machine. Part No. KGV180.1550.110.80. Make:-Plasser or equivalent.	BPL/W/TM/2015-16/25/45 dtd.21.03.16	111825	Yes	Yes	No	No	No	TC to be done
14	Induction heater required for track machine. Capacity 4 KVA. Make:-UNITECH or equivalent.	BPL/W/TM/2015-16/25/45 dtd.21.03.16	79925	Yes	Yes	No	No	No	TC to be done
15	Wear plate required for BCM machines. Make:- INDIGENOUS	BPL/W/TM/2015-16/25/45 dtd.21.03.16	163234	Yes	Yes	No	No	No	TC to be done

Office of the DyCE(TM)/BPL
TENDER UNDER FINALISATION (Dy.CE/TM/BPL)

August , 2016									
S.N.	Name of work	NIT No.	Value of tender in Rs.	Stage of Tender					
				Briefing note and comparative statement	Vetting of Briefing Note	Tender Committee minutes finalised	Tender Committee minutes acceptance	Acceptance letter issued	Remark
				Yes/No	Yes/No	Yes/No	Yes/No	Yes/No	
16	Spares Required for Cummins engine NTA743 of BRM-101 Machine during IOH	16-17/PAC/08 dtd. 17.05.16	87625	Yes	Yes	No	No	No	TC to be done
17	Air compressor Required for Track Machine	16-17/PAC/01 dtd. 17.05.16	87096	Yes	Yes	No	No	No	TC to be done
18	Spares Required for Repairing of self starter	16-17/PAC/26 dtd. 17.05.16	60219	Yes	Yes	No	No	No	TC to be done
19	Air compressor Required for BCM-322 Machine	16-17/PAC/27 dtd. 17.05.16	110250	Yes	Yes	No	No	No	TC to be done
20	Lifting cylinder Required for BCM Machines	16-17/PAC/12 dtd. 17.05.16	174320	Yes	Yes	No	No	No	TC to be done
21	Spares Required for Repaireing of Engine KTA1150L at ZTMD/HBJ	16-17/PAC/18 dtd. 17.05.16	126504	Yes	Yes	No	No	No	TC to be done
22	Spares Required for BRM-110 During IOH	16-17/PAC/19 dtd. 17.05.16	135433	Yes	Yes	No	No	No	TC to be done
23	Spares Required for CUMMINS engine of BRM-101 Machine during IOH	16-17/PAC/21 dtd. 17.05.16	139690	Yes	Yes	No	No	No	TC to be done
24	Air cleaner filter Required for track machines	16-17/PAC/22 dtd. 17.05.16	139421	Yes	Yes	No	No	No	TC to be done
25	Spares Required for repairing of PT pump & cylinder head of Cummins engine.	16-17/PAC/23 dtd. 17.05.16	34566	Yes	Yes	No	No	No	TC to be done
26	Air cleaner filter Required for track machines	16-17/PAC/24 dtd. 17.05.16	67278	Yes	Yes	No	No	No	TC to be done

Office of the DyCE(TM)/BPL
TENDER UNDER FINALISATION (Dy.CE/TM/BPL)

August , 2016									
S.N.	Name of work	NIT No.	Value of tender in Rs.	Stage of Tender					Remark
				Briefing note and comparative statement	Vetting of Briefing Note	Tender Committee minutes finalised	Tender Committee minutes acceptance	Acceptance letter issued	
				Yes/No	Yes/No	Yes/No	Yes/No	Yes/No	
27	Spares Required for Duetz engine of BCM-319, BCM-345 & BCM-322 Machine	16-17/PAC/29 dtd. 17.05.16	134913	Yes	Yes	No	No	No	TC to be done
28	Hydraulic motor Required for Track Machines	16-17/PAC/30 dtd. 17.05.16	144594	Yes	Yes	No	No	No	TC to be done
29	Spares Required for Track Machine	16-17/PAC/16 dtd. 17.05.16	141511	Yes	Yes	No	No	No	TC to be done
30	Air compressor Required for DUO-8122 Machine	16-17/PAC/20 dtd. 17.05.16	118536	Yes	Yes	No	No	No	TC to be done
31	Filter Required for NEW Track Machines	16-17/PAC/33 dtd. 17.05.16	45929	Yes	Yes	No	No	No	TC to be done