

Office of the DyCE(TM)/BPL
Status of released of Security Deposit

January, 2017

Sr.No.	Name of work	Name of firm	Date of physical completion of work	Date of letter sent to Finance for release	Date of release	Remerks
1	Spares required for repairing of Duetz engine of BCM machine	M/s. South Calcutta Diesel Pvt. Ltd.	06.02.2016	02.01.2017	04.01.2017	
2	Engine filter required for duetz engine of mobile bridge inspection	M/s. South Calcutta Diesel Pvt. Ltd.	10.12.2015	02.01.2017	04.01.2017	
3	Spares required for repairing of Duetz engine of BCM machine	M/s. South Calcutta Diesel Pvt. Ltd.	18.02.2016	02.01.2017	04.01.2017	
4	Fasteners required for track machine	M/s. Vibrant Enginners	03.12.2015	03.01.2017	09.01.2017	
5	Fasteners required for track machine	M/s. Empric Engineers	08.02.2015	03.01.2017	09.01.2017	
6	Repairing of commissioning of bucket unit emergency back up & creep unit	M/s. HI-Tron Engineers	05.03.2016	17.01.2017	24.01.2017	
7	Repairing of commissioning of bucket unit emergency back up & creep unit	M/s. HI-Tron Engineers	25.02.2016	17.01.2017	24.01.2017	
8	Air drayer required for track machine	M/s. Agromach Spares Corporation	11.03.2016	27.01.2017		
9	Cutting chain assembly required for track machine	M/s. Anand Traders	05.08.2015	30.01.2017		
10	Measuring transducer required for track machine	M/s. Anand Traders	23.12.2015	30.01.2017		
11	Brake shoe required for track machine	M/s. Anand Traders	18.03.2015	30.01.2017		
12	Brake shoe required for track machine	M/s. Anand Traders	23.07.2015	30.01.2017		
13	Trolley wheel required for track machine	M/s. Anand Traders	18.06.2015	30.01.2017		

Office of the DyCE(TM)/BPL
Status of released of Security Deposit

January, 2017

Sr.No.	Name of work	Name of firm	Date of physical completion of work	Date of letter sent to Finance for release	Date of release	Remerks
14	50mm square pin required for track machine	M/s. Anand Traders	05.11.2015	30.01.2017		
15	Pneumatic valve with single coil for UTV machine	M/s. Anand Traders	16.11.2015	30.01.2017		
16	Proportional transducer required for CSM machine	M/s. Anand Traders	01.02.2016	30.01.2017		
17	Drive shaft required for track machine	M/s. Anand Traders	28.09.2015	30.01.2017		
18	Screen floor set required for BCM machine	M/s. Anand Traders	13.07.2015	30.01.2017		
19	UJ cross required for cardon shaft for BRM machine	M/s. Anand Traders	16.11.2015	30.01.2017		
20	Drive shaft required for mp-2003machine	M/s. Khandelwal Metal Engg. Works	23.12.2015	30.01.2017		
21	Wear plate required for BRM 101 &110machine	M/s. Khandelwal Metal Engg. Works	26.12.2015	30.01.2017		
22	Wear plate required for BCM machine	M/s. Khandelwal Metal Engg. Works	26.12.2015	30.01.2017		
23	Rail clamp disc required for BRM 101machine	M/s. Khandelwal Metal Engg. Works	18.05.2015	30.01.2017		
24	Special head bolt with nut & washer required for BCM machine	M/s. Khandelwal Metal Engg. Works	03.09.2015	30.01.2017		