

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO04102  
Form No. F/BR/ICF/002

Type : WGACCN

Built Year : 2004

Make : RCF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	10.5	66%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	10.5	66%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 3 Other End - EAST : -10, WEST : -7  
Start Date : 15-Jan-2019, Completion Date : 21-Jan-2019, Net Repair Days : 6, Total Man Hours : 1528

ANASTA PRASAD - JE	K K DEHARIA - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	-----------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO04202  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2004

Make : RCF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	32	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	32	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	10	25%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 3 Other End - EAST : 0, WEST : 0  
Start Date : 05-Apr-2018, Completion Date : 13-Apr-2018, Net Repair Days : 8, Total Man Hours : 1868

HAMANT JADAV - JE	M L KOLI - JE	T K PANJA - SSE	A.R.R. KURUP - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	-----------------	------------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO04204  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2004

Make : RCF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	48	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -5, WEST : 0 Other End - EAST : -10, WEST : -8  
Start Date : 06-Apr-2018, Completion Date : 19-Apr-2018, Net Repair Days : 12, Total Man Hours : 1748

P S RATHORE - JE	NISHANK VERMA - JE	ARUN SINGH - SSE	A.R.R. KURUP - SSE In-charge	Verified By:QU-Incharge
------------------	--------------------	------------------	------------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO04205  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2004

Make : RCF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	20	50%		Window Bar	48	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : -6 Other End - EAST : -8, WEST : -8  
Start Date : 04-Apr-2018, Completion Date : 11-Apr-2018, Net Repair Days : 7, Total Man Hours : 1904

P N VISHWKARMA - SSE	U S BAJPAI - SSE	T K PANJA - SSE	A.R.R. KURUP - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	-----------------	------------------------------	-------------------------



# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO04210  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2004

Make : RCF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -5, WEST : -4 Other End - EAST : -4, WEST : -4  
Start Date : 29-Aug-2018, Completion Date : 08-Sep-2018, Net Repair Days : 10, Total Man Hours : 1700

U S BAJPAI - SSE	P N VISHWKARMA - SSE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO04703  
Form No. F/BR/ICF/002

Type : SLRD

Built Year : 2004

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	14	88%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	14	88%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	74%		Window Bar	24	29%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -8, WEST : -6 Other End - EAST : 5, WEST : 2  
Start Date : 13-Jul-2018, Completion Date : 21-Jul-2018, Net Repair Days : 8, Total Man Hours : 2052

U S BAJPAI - SSE	P N VISHWKARMA - SSE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO04707  
Form No. F/BR/ICF/002

Type : SLRD

Built Year : 2004

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Blue	Centre Stiffner for Headstock	4	100%	Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	16	100%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	1	14%	Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	10	53%		Window Bar	20	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -10, WEST : -8 Other End - EAST : 2, WEST : 10  
Start Date : 04-Sep-2018, Completion Date : 12-Sep-2018, Net Repair Days : 8, Total Man Hours : 1776

P S RATHORE - JE	K K DEHARIA - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	------------------	-----------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO05051


Type : WGACCW

Built Year : 2005

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	5	31%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 5 Other End - EAST : -4, WEST : -5

Start Date : 12-Feb-2019, Completion Date : 22-Feb-2019, Net Repair Days : 10, Total Man Hours : 1312

K K TRIPATHI - SSE	H R KANNOJE - SSE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	-------------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO05151


Type : WGSCZAC

Built Year : 2005

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6.5	41%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		4%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -7, WEST : -3 Other End - EAST : -7, WEST : 2

Start Date : 25-Feb-2019, Completion Date : 08-Mar-2019, Net Repair Days : 11, Total Man Hours : 1296

K K DEHARIA - JE	ANASTA PRASAD - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	--------------------	-----------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO05153  
Form No. F/BR/ICF/002

Type : WGSCZAC

Built Year : 2005

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Blue	Centre Stiffner for Headstock	4	100%	Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Red	Sole Bar	6.5	41%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		100%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -5, WEST : 5 Other End - EAST : -7, WEST : -3  
Start Date : 29-Sep-2018, Completion Date : 13-Oct-2018, Net Repair Days : 13, Total Man Hours : 1288

S K SHARMA - SSE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	-----------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO05224  
Form No. F/BR/ICF/002

Type : CN

Built Year : 2005

Make : RCF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Blue	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Blue	Aux. Head stock	4	100%	Light Green	Sole Bar	16	100%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Yellow	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	29	73%		Window Bar	50	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -10, WEST : -5 Other End - EAST : -3, WEST : -4  
Start Date : 23-May-2018, Completion Date : 31-May-2018, Net Repair Days : 8, Total Man Hours : 1756

M L KOLI - JE	HAMANT JADAV - JE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------	-------------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO05225  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2005

Make : RCF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6	38%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	22	55%		Window Bar	48	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : -5 Other End - EAST : 3, WEST : 5  
Start Date : 02-Apr-2018, Completion Date : 16-Apr-2018, Net Repair Days : 13, Total Man Hours : 1260

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	ARUN SINGH - SSE	A.R.R. KURUP - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	------------------	------------------------------	-------------------------



# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO05226  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2005

Make : RCF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Blue	Centre Stiffner for Headstock	4	100%	Green	Floor Stiffner for Headstock	4	100%
Blue	Aux. Head stock	4	100%	Pink	Sole Bar	16	100%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	32	80%		Window Bar	58	32%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 5 Other End - EAST : -2, WEST : 3  
Start Date : 04-Sep-2018, Completion Date : 13-Sep-2018, Net Repair Days : 9, Total Man Hours : 1852

P N VISHWKARMA - SSE	U S BAJPAI - SSE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO05227  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2005

Make : RCF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	14	88%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	14	88%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	42	23%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : 3 Other End - EAST : 2, WEST : -5  
Start Date : 21-Jun-2018, Completion Date : 29-Jun-2018, Net Repair Days : 8, Total Man Hours : 1732

NISHANK VERMA - JE	P S RATHORE - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	-----------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO05263  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2005

Make : RCF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		0%		Door Top/Roof Patch		100%
	Window Module		0%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 5 Other End - EAST : -5, WEST : -5  
Start Date : 13-Dec-2018, Completion Date : 21-Dec-2018, Net Repair Days : 8, Total Man Hours : 1776

S K SHARMA - SSE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	-----------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO05266  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2005

Make : RCF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	14	88%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	14	88%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	52	28%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -10, WEST : -6 Other End - EAST : -10, WEST : -6  
Start Date : 28-Mar-2018, Completion Date : 06-Apr-2018, Net Repair Days : 9, Total Man Hours : 1816

P N VISHWKARMA - SSE	U S BAJPAI - SSE	MANOJ AGARAWAL - SSE	A.R.R. KURUP - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	----------------------	------------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO05272  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2005

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	50	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : -5 Other End - EAST : -10, WEST : -5  
Start Date : 22-Dec-2018, Completion Date : 03-Jan-2019, Net Repair Days : 6, Total Man Hours : 1940

HAMANT JADAV - JE	M L KOLI - JE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO05407  
Form No. F/BR/ICF/002

Type : GS

Built Year : 2005

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	68	38%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : -10 Other End - EAST : -8, WEST : -3  
Start Date : 10-Apr-2018, Completion Date : 24-Apr-2018, Net Repair Days : 13, Total Man Hours : 2100

M L KOLI - JE	HAMANT JADAV - JE	ARUN SINGH - SSE	A.R.R. KURUP - SSE In-charge	Verified By:QU-Incharge
---------------	-------------------	------------------	------------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO05804  
Form No. F/BR/ICF/002

Type : WCB

Built Year : 2005

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	8	42%		Window Bar	22	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -6, WEST : -2 Other End - EAST : -7, WEST : -10  
Start Date : 28-May-2018, Completion Date : 09-Jun-2018, Net Repair Days : 12, Total Man Hours : 2296

U S BAJPAI - SSE	P N VISHWKARMA - SSE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO06206


Type : WGSCN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Green	Diagonal	4	100%	Orange	Logitudinal Channel Structure	2	100%
Dark Blue	Aux. Head stock	2	100%	Pink	Sole Bar	5	31%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	40%		Bottom Wall Part	5	31%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	12	30%
	Window Bar	34	18%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	28	100%								

End Drooping: Rotary End - EAST : -8, WEST : -7 Other End - EAST : 5, WEST : -5  
Start Date : 11-Jun-2018, Completion Date : 19-Jun-2018, Net Repair Days : 8, Total Man Hours : 1384

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	T K PANJA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
------------------	-----------------------	-----------------	------------------	-------------------------



# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO06220


Type : CN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Teal	Diagonal	4	100%	Orange	Logitudinal Channel Structure	2	100%
Dark Blue	Aux. Head stock	0	0%	Pink	Sole Bar	4	25%	Blue	Draft Gear Bracket	0	0%
Yellow	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	3	8%
	Window Bar	22	12%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -10, WEST : -3 Other End - EAST : -10, WEST : -10

Start Date : 16-Apr-2018, Completion Date : 27-Apr-2018, Net Repair Days : 11, Total Man Hours : 1480

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	ARUN SINGH - SSE	A.R.R. KURUP - SSE	Verified By:QU-Incharge
-----------------------	------------------	------------------	--------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. : ECO06229  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2006

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Blue	Centre Stiffner for Headstock	4	100%	Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	13	81%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	13	81%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	20	50%		Window Bar	40	22%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 10, WEST : 8 Other End - EAST : -7, WEST : -10  
Start Date : 08-Jun-2018, Completion Date : 15-Jun-2018, Net Repair Days : 7, Total Man Hours : 1673

PANKAJ KU SINGH - JE	S K SHARMA - SSE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	-----------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO06232  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2006

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	14.5	91%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	14.5	91%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	7	18%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 4, WEST : 0 Other End - EAST : 6, WEST : 6  
Start Date : 07-Jun-2018, Completion Date : 13-Jun-2018, Net Repair Days : 6, Total Man Hours : 1600

P N VISHWKARMA - SSE	U S BAJPAI - SSE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. : ECO06234  
Form No. F/BR/ICF/002

Type : WGSCN

Built Year : 2006

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Blue	Centre Stiffner for Headstock	4	100%	Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	12	75%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	12	75%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	20	50%		Window Bar	50	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 4 Other End - EAST : 0, WEST : 6  
Start Date : 27-Mar-2018, Completion Date : 07-Apr-2018, Net Repair Days : 11, Total Man Hours : 1492

PANKAJ KU SINGH - JE	S K SHARMA - SSE	ARUN SINGH - SSE	A.R.R. KURUP - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------	------------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO06401


Type : GS

Built Year : 2006

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	11.5	72%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	11.5	72%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 2 Other End - EAST : -6, WEST : -10

Start Date : 28-Aug-2018, Completion Date : 07-Sep-2018, Net Repair Days : 10, Total Man Hours : 1600

HAMANT JADAV - JE	M L KOLI - JE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO06408  
Form No. F/BR/ICF/002

Type : GS

Built Year : 2018

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	12	75%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	12	75%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	54	30%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : -2 Other End - EAST : -4, WEST : -5  
Start Date : 03-Oct-2018, Completion Date : 12-Oct-2018, Net Repair Days : 9, Total Man Hours : 1496

M L KOLI - JE	HAMANT JADAV - JE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------	-------------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO06413  
Form No. F/BR/ICF/002

Type : GS

Built Year : 2006

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Blue	Centre Stiffner for Headstock	4	100%	Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	16	100%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	24	60%		Window Bar	62	35%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -8, WEST : -8 Other End - EAST : 10, WEST : 10  
Start Date : 04-Jun-2018, Completion Date : 09-Jun-2018, Net Repair Days : 6, Total Man Hours : 2186

PANKAJ KU SINGH - JE	S K SHARMA - SSE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	-----------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO06601


Type : WGSCZ

Built Year : 2006

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Green	Centre Stiffner for Headstock	4	100%	Blue	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	12.5	78%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	12.5	78%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 0 Other End - EAST : 0, WEST : 0

Start Date : 21-Apr-2018, Completion Date : 28-Apr-2018, Net Repair Days : 7, Total Man Hours : 1672

HAMANT JADAV - JE	M L KOLI - JE	ARUN SINGH - SSE	A.R.R. KURUP - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	------------------	------------------------------	-------------------------



# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO06603  
Form No. F/BR/ICF/002

Type : WGSCZ

Built Year : 2006

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Green	Centre Stiffner for Headstock	4	100%	Yellow	Floor Stiffner for Headstock	4	100%
Blue	Aux. Head stock	4	100%	Pink	Sole Bar	12	75%	Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	12	75%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	20	50%		Window Bar	50	28%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -10, WEST : -10 Other End - EAST : -10, WEST : -8  
Start Date : 26-Apr-2018, Completion Date : 08-May-2018, Net Repair Days : 11, Total Man Hours : 1754

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-----------------------	------------------	-----------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO07202


Type : WGSCN

Built Year : 2007

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	4	10%
	Window Bar	14	8%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -4, WEST : -5 Other End - EAST : 8, WEST : 4

Start Date : 11-Jun-2018, Completion Date : 19-Jun-2018, Net Repair Days : 8, Total Man Hours : 1016

NISHANK VERMA - JE	P S RATHORE - JE	T K PANJA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
--------------------	------------------	-----------------	------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO07205


Type : WGSCN

Built Year : 2007

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	14	35%
	Window Bar	48	26%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -6, WEST : -4 Other End - EAST : -5, WEST : -7

Start Date : 12-May-2018, Completion Date : 19-May-2018, Net Repair Days : 7, Total Man Hours : 1320

K K TRIPATHI - SSE	H R KANNOJE - SSE	ARUN SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
--------------------	-------------------	------------------	------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO07207


Type : WGSCN

Built Year : 2007

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	10	25%
	Window Bar	9	23%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -5, WEST : -3 Other End - EAST : -3, WEST : -3

Start Date : 23-May-2018, Completion Date : 30-May-2018, Net Repair Days : 7, Total Man Hours : 1392

H R KANNOJE - SSE	K K TRIPATHI - SSE	ARUN SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
-------------------	--------------------	------------------	------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO07209


Type : WGSCN

Built Year : 2007

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	14	35%
	Window Bar	36	20%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -6, WEST : -3 Other End - EAST : -5, WEST : -3

Start Date : 02-Jul-2018, Completion Date : 06-Jul-2018, Net Repair Days : 5, Total Man Hours : 1336

U S BAJPAI - SSE	P N VISHWKARMA - SSE	ARUN SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
------------------	----------------------	------------------	------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO07211


Type : WGSCN

Built Year : 2007

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	7	18%
	Window Bar	28	15%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -8, WEST : -8 Other End - EAST : -10, WEST : -10

Start Date : 24-May-2018, Completion Date : 31-May-2018, Net Repair Days : 7, Total Man Hours : 1288

S K SHARMA - SSE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
------------------	----------------------	-----------------	------------------	-------------------------



# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO07213


Type : WGSCN

Built Year : 2007

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	9	23%
	Window Bar	20	11%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -6, WEST : -5 Other End - EAST : -5, WEST : -8

Start Date : 11-Jun-2018, Completion Date : 18-Jun-2018, Net Repair Days : 7, Total Man Hours : 1316

K K TRIPATHI - SSE	H R KANNOJE - SSE	ARUN SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
--------------------	-------------------	------------------	------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO07216


Type : WGSCN

Built Year : 2007

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Green	Diagonal	4	100%	Orange	Logitudinal Channel Structure	2	100%
Blue	Aux. Head stock	2	100%	Pink	Sole Bar	4	25%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	14	35%
	Window Bar	36	20%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -10, WEST : -5 Other End - EAST : -5, WEST : -5

Start Date : 09-Jul-2018, Completion Date : 14-Jul-2018, Net Repair Days : 6, Total Man Hours : 1156

S K SHARMA - SSE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
------------------	----------------------	-----------------	------------------	-------------------------



# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO07224


Type : CN

Built Year : 2007

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	10	25%
	Window Bar	36	20%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -5, WEST : 0 Other End - EAST : 2, WEST : -5

Start Date : 25-May-2018, Completion Date : 02-Jun-2018, Net Repair Days : 8, Total Man Hours : 1300

H R KANNOJE - SSE	K K TRIPATHI - SSE	ARUN SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
-------------------	--------------------	------------------	------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO07232


Type : CN

Built Year : 2007

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Green	Diagonal	4	100%	Orange	Logitudinal Channel Structure	2	100%
Blue	Aux. Head stock	2	100%	Pink	Sole Bar	4	25%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	11	28%
	Window Bar	28	15%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : 0, WEST : 10 Other End - EAST : 2, WEST : 0

Start Date : 26-May-2018, Completion Date : 02-Jun-2018, Net Repair Days : 7, Total Man Hours : 1228

S K SHARMA - SSE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
------------------	----------------------	-----------------	------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO07235


Type : WGSCN

Built Year : 2007

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4.5	28%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4.5	28%		Body panel/patch		0%
	Door Top/Roof Patch		100%		Seat Bracket Rail		0%		Window Sill	12	30%
	Window Bar	20	11%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	25	100%								

End Drooping: Rotary End - EAST : -6, WEST : -5 Other End - EAST : -3, WEST : -5  
Start Date : 14-Jun-2018, Completion Date : 21-Jun-2018, Net Repair Days : 7, Total Man Hours : 1292

P N VISHWKARMA - SSE	U S BAJPAI - SSE	ARUN SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
----------------------	------------------	------------------	------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ECO07411


Type : GS

Built Year : 2007

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	9.5	59%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	9.5	59%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	21	53%		Window Bar	60	34%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 3 Other End - EAST : -5, WEST : -4

Start Date : 19-May-2018, Completion Date : 29-May-2018, Net Repair Days : 9, Total Man Hours : 1548

P N VISHWKARMA - SSE	U S BAJPAI - SSE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair


Coach No. :ECO07414  
Form No. F/BR/ICF/002

Type : GS

Built Year : 2007

Make : ICF

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	13.5	84%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	13.5	84%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	26	65%		Window Bar	62	35%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 6 Other End - EAST : 0, WEST : 0  
Start Date : 24-May-2018, Completion Date : 02-Jun-2018, Net Repair Days : 9, Total Man Hours : 1528

U S BAJPAI - SSE	P N VISHWKARMA - SSE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------	----------------------------	-------------------------