

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06455


Type : GS

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8	50%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	52	29%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 2 Other End - EAST : 5, WEST : 6
Start Date : 26-Mar-2019, Completion Date : 02-Apr-2019, Net Repair Days : 7, Total Man Hours : 1445

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05245


Type : WGSCN

Built Year : 2005

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	0	0%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Bottom Wall Part	0	0%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	14	35%
	Window Bar	15	8%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : -10, WEST : -8 Other End - EAST : -10, WEST : -9
Start Date : 12-Apr-2019, Completion Date : 22-Apr-2019, Net Repair Days : 9, Total Man Hours : 824

PANKAJ KU SINGH - JE	ALOK CHOUDHARY - JE	S K SHARMA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
----------------------	---------------------	------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06264


Type : CN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	30	75%
	Window Bar	48	26%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -10, WEST : -8 Other End - EAST : -8, WEST : -10
Start Date : 25-Apr-2019, Completion Date : 02-May-2019, Net Repair Days : 7, Total Man Hours : 1090

M L KOLI - JE	HAMANT JADAV - JE	S K SHARMA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
---------------	-------------------	------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05232


Type : WGSCN

Built Year : 2005

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Bottom Wall Part	0	0%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	0	0%
	Window Bar	0	0%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : -5, WEST : -7 Other End - EAST : -7, WEST : -6
Start Date : 20-May-2019, Completion Date : 24-May-2019, Net Repair Days : 5, Total Man Hours : 0

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
------------------	----------------------	------------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07211


Type : CN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	6	38%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	72	39%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 4 Other End - EAST : -2, WEST : 5
Start Date : 07-Sep-2019, Completion Date : 14-Sep-2019, Net Repair Days : 7, Total Man Hours : 1072

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06765


Type : GSLRD

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	14	88%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	14	88%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	10	53%		Window Bar	16	19%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 3, WEST : 7 Other End - EAST : -4, WEST : -8
Start Date : 04-Jun-2019, Completion Date : 14-Jun-2019, Net Repair Days : 10, Total Man Hours : 1592

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05248


Type : WGSCN

Built Year : 2005

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	2	40%		Bottom Wall Part	0	0%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	0	0%
	Window Bar	0	0%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : -6, WEST : -4 Other End - EAST : -5, WEST : -7

Start Date : 15-Jun-2019, Completion Date : 25-Jun-2019, Net Repair Days : 9, Total Man Hours : 584

K K DEHARIA - JE	ANASTA PRASAD - JE	S S SHIVHARE - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
------------------	--------------------	--------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05237


Type : WGSCN

Built Year : 2005

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Blue	Headstock Beam	0	0%	Red	Diagonal	4	100%	Green	Logitudinal Channel Structure	0	0%
Black	Aux. Head stock	0	0%	Yellow	Sole Bar	0.5	3%	Light Blue	Draft Gear Bracket	0	0%
Orange	Trough floor	0	0%		Bottom Wall Part	0.5	3%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	12	30%
	Window Bar	50	27%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	3	100%								

End Drooping: Rotary End - EAST : 0, WEST : 3 Other End - EAST : -5, WEST : -4
Start Date : 11-Jul-2019, Completion Date : 19-Jul-2019, Net Repair Days : 8, Total Man Hours : 968

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
----------------------	------------------	------------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR08908


Type : WGACCN

Built Year : 2008

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		3%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 3, WEST : 3 Other End - EAST : 5, WEST : 3
Start Date : 21-Oct-2019, Completion Date : 30-Oct-2019, Net Repair Days : 9, Total Man Hours : 1248

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06757


Type : GSLRD

Built Year : 2000

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	0	0%	Blue	Centre Stiffner for Headstock	0	0%	Blue	Floor Stiffner for Headstock	0	0%
Blue	Aux. Head stock	0	0%	Yellow	Sole Bar	6	38%	Blue	Draft Gear Bracket	0	0%
Yellow	Trough floor	0	0%	Blue	Centre plate	0	0%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	12	30%		Window Bar	22	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -6, WEST : -7 Other End - EAST : -7, WEST : -80
Start Date : 25-Oct-2019, Completion Date : 05-Nov-2019, Net Repair Days : 10, Total Man Hours : 936

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071022


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6.5	41%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	40	23%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 4 Other End - EAST : -3, WEST : -5
Start Date : 23-Oct-2019, Completion Date : 02-Nov-2019, Net Repair Days : 10, Total Man Hours : 0

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071021


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8	50%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	20	50%		Window Bar	40	23%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : 5 Other End - EAST : -7, WEST : 3
Start Date : 25-Oct-2019, Completion Date : 05-Nov-2019, Net Repair Days : 10, Total Man Hours : 1176

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071025


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8	50%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	40	23%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -8, WEST : -2 Other End - EAST : 8, WEST : 6
Start Date : 30-Oct-2019, Completion Date : 08-Nov-2019, Net Repair Days : 9, Total Man Hours : 1003

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-----------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071047


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	7.5	47%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	7.5	47%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -4, WEST : 2 Other End - EAST : -2, WEST : 6
Start Date : 25-Oct-2019, Completion Date : 04-Nov-2019, Net Repair Days : 9, Total Man Hours : 0

HAMANT JADAV - JE	M L KOLI - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071043


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	7.5	47%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	7.5	47%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : -7 Other End - EAST : -6, WEST : -4
Start Date : 26-Oct-2019, Completion Date : 06-Nov-2019, Net Repair Days : 10, Total Man Hours : 1064

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071050


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8	50%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 4, WEST : 2 Other End - EAST : 3, WEST : 0
Start Date : 30-Oct-2019, Completion Date : 06-Nov-2019, Net Repair Days : 7, Total Man Hours : 1296

M L KOLI - JE	HAMANT JADAV - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------	-------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071038


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8.5	53%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8.5	53%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	46	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : 0 Other End - EAST : -4, WEST : -3
Start Date : 26-Nov-2019, Completion Date : 05-Dec-2019, Net Repair Days : 9, Total Man Hours : 1536

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06238


Type : WGSCN

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	10.5	66%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	10.5	66%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	24	60%		Window Bar	46	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 0 Other End - EAST : 2, WEST : -3

Start Date : 03-Dec-2019, Completion Date : 10-Dec-2019, Net Repair Days : 7, Total Man Hours : 1616

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06122


Type : WGACCN

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6.5	41%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		12%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 0 Other End - EAST : 5, WEST : 3
Start Date : 20-Dec-2019, Completion Date : 01-Jan-2020, Net Repair Days : 11, Total Man Hours : 1076

P N VISHWKARMA - SSE	T R LARRE - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	----------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06224


Type : WGSCN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	1	50%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	1	50%		Sole Bar	3	19%		Draft Gear Bracket	1	50%
	Trough floor	2	40%		Bottom Wall Part	3	19%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	10	25%
	Window Bar	22	12%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	17	100%								

End Drooping: Rotary End - EAST : -6, WEST : -2 Other End - EAST : -8, WEST : -6
Start Date : 29-Mar-2019, Completion Date : 06-Apr-2019, Net Repair Days : 8, Total Man Hours : 1096

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
------------------	----------------------	------------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05254


Type : WGSCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6	38%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : -2 Other End - EAST : -3, WEST : -6
Start Date : 01-Apr-2019, Completion Date : 08-Apr-2019, Net Repair Days : 7, Total Man Hours : 1551

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-----------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05127


Type : WGACCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	5.5	34%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5.5	34%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		5%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : -3 Other End - EAST : -5, WEST : -3
Start Date : 06-Apr-2019, Completion Date : 18-Apr-2019, Net Repair Days : 11, Total Man Hours : 1048

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05230


Type : CN

Built Year : 2005

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	1	50%		Diagonal	4	100%		Logitudinal Channel Structure	0	0%
	Aux. Head stock	0	0%		Sole Bar	3	19%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Bottom Wall Part	3	19%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	0	0%
	Window Bar	6	3%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	17	100%								

End Drooping: Rotary End - EAST : -6, WEST : -8 Other End - EAST : -8, WEST : -8
Start Date : 16-May-2019, Completion Date : 25-May-2019, Net Repair Days : 9, Total Man Hours : 880

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	S K SHARMA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
---------------------	----------------------	------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06740


Type : SLRD

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	13	81%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	13	81%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	10	53%		Window Bar	14	17%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : -3 Other End - EAST : -5, WEST : 0
Start Date : 01-Jun-2019, Completion Date : 13-Jun-2019, Net Repair Days : 11, Total Man Hours : 1456

K K TRIPATHI - SSE	H R KANNOJE - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	-------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05113


Type : WGACCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4.5	28%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4.5	28%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		2%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 6 Other End - EAST : 4, WEST : 6
Start Date : 07-Dec-2019, Completion Date : 17-Dec-2019, Net Repair Days : 9, Total Man Hours : 1440

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071051


Type : GSLRD

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	11.5	72%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	11.5	72%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	12	63%		Window Bar	22	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -4, WEST : -3 Other End - EAST : 3, WEST : 4

Start Date : 12-Dec-2019, Completion Date : 20-Dec-2019, Net Repair Days : 8, Total Man Hours : 1840

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07702


Type : GSRD

Built Year : 2007

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	2	50%		Floor Stiffner for Headstock	2	50%
	Aux. Head stock	2	50%		Sole Bar	7	44%		Draft Gear Bracket	1	50%
	Trough floor	1	14%		Centre plate	1	50%		SoleBar Stiffner	4	100%
	Bottom Wall Part	7	44%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	78%		Window Bar	48	28%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : 0 Other End - EAST : 0, WEST : -2
Start Date : 20-Dec-2019, Completion Date : 01-Jan-2020, Net Repair Days : 11, Total Man Hours : 860

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07604


Type : WGSCZ

Built Year : 2007

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	16	100%	Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 1 Other End - EAST : -2, WEST : -5
Start Date : 26-Dec-2019, Completion Date : 03-Jan-2020, Net Repair Days : 8, Total Man Hours : 1204

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06738


Type : GSLRD

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	13	81%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	13	81%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	9	47%		Window Bar	16	19%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 4, WEST : 5 Other End - EAST : 5, WEST : 4
Start Date : 07-May-2019, Completion Date : 21-May-2019, Net Repair Days : 13, Total Man Hours : 1640

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06505


Type : GS

Built Year : 2006

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	16	100%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	56	31%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : -5 Other End - EAST : 2, WEST : 3
Start Date : 29-Apr-2019, Completion Date : 06-May-2019, Net Repair Days : 7, Total Man Hours : 1632

M L KOLI - JE	HAMANT JADAV - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------	-------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07415/C


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	7.5	47%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	7.5	47%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	28%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 4 Other End - EAST : -3, WEST : -2
Start Date : 26-Apr-2019, Completion Date : 03-May-2019, Net Repair Days : 7, Total Man Hours : 0

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05221


Type : WGSCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	10	63%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	10	63%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	20	50%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 0 Other End - EAST : -10, WEST : -8
Start Date : 01-Apr-2019, Completion Date : 09-Apr-2019, Net Repair Days : 11, Total Man Hours : 1268

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05053


Type : WGACCW

Built Year : 2005

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	6	38%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		7%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -10, WEST : -8 Other End - EAST : -7, WEST : -9
Start Date : 30-Mar-2019, Completion Date : 06-Apr-2019, Net Repair Days : 7, Total Man Hours : 1524

HAMANT JADAV - JE	M L KOLI - JE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06493


Type : GS

Built Year : 2006

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	12.5	78%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	12.5	78%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : -2 Other End - EAST : -4, WEST : -5
Start Date : 08-May-2019, Completion Date : 21-May-2019, Net Repair Days : 12, Total Man Hours : 0

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06614


Type : WGSCZ

Built Year : 2006

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6	38%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		100%
	Window Module		0%		Window Sill	26	65%		Window Bar	46	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 7, WEST : 7 Other End - EAST : -5, WEST : -7
Start Date : 13-May-2019, Completion Date : 23-May-2019, Net Repair Days : 10, Total Man Hours : 1104

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR04067


Type : WGACCW

Built Year : 2004

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	5	31%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		4%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -8, WEST : 4 Other End - EAST : -6, WEST : 2
Start Date : 04-Jun-2019, Completion Date : 14-Jun-2019, Net Repair Days : 10, Total Man Hours : 1164

K K TRIPATHI - SSE	H R KANNOJE - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	-------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06502


Type : GS

Built Year : 2006

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	11	69%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	11	69%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	40	22%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 0 Other End - EAST : 0, WEST : 0
Start Date : 01-Jun-2019, Completion Date : 12-Jun-2019, Net Repair Days : 10, Total Man Hours : 1208

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06756


Type : GSLRD

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	11	69%		Draft Gear Bracket	2	100%
	Trough floor	0	0%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	11	69%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	10	53%		Window Bar	16	19%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 0 Other End - EAST : 0, WEST : 0
Start Date : 29-May-2019, Completion Date : 08-Jun-2019, Net Repair Days : 10, Total Man Hours : 1232

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05052


Type : WGACCW

Built Year : 2005

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Green	Centre Stiffner for Headstock	4	100%	Red	Floor Stiffner for Headstock	4	100%
Blue	Aux. Head stock	4	100%	Yellow	Sole Bar	8	50%	Blue	Draft Gear Bracket	2	100%
Red	Trough floor	2	29%	Red	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		4%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : -5 Other End - EAST : 0, WEST : -3
Start Date : 12-Oct-2019, Completion Date : 24-Oct-2019, Net Repair Days : 11, Total Man Hours : 1232

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06761


Type : GSLRD

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	13	81%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	13	81%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	10	53%		Window Bar	14	17%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : 0 Other End - EAST : -2, WEST : -5
Start Date : 14-Jun-2019, Completion Date : 22-Jun-2019, Net Repair Days : 8, Total Man Hours : 1696

PANKAJ KU SINGH - JE	ALOK CHOUDHARY - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	---------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06413


Type : GS

Built Year : 2019

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	7.5	47%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	7.5	47%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	46	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 5 Other End - EAST : 4, WEST : -3
Start Date : 30-May-2019, Completion Date : 10-Jun-2019, Net Repair Days : 10, Total Man Hours : 1368

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05227


Type : WGSCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6	38%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : -5 Other End - EAST : 3, WEST : 2
Start Date : 10-Jun-2019, Completion Date : 17-Jun-2019, Net Repair Days : 7, Total Man Hours : 1119

K K DEHARIA - JE	ANASTA PRASAD - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	--------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06767


Type : GSLRD

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	14	88%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	14	88%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	9	47%		Window Bar	12	14%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -10, WEST : -10 Other End - EAST : 4, WEST : 4
Start Date : 15-Jun-2019, Completion Date : 26-Jun-2019, Net Repair Days : 10, Total Man Hours : 1648

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-----------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05242


Type : WGSCN

Built Year : 2005

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	2	40%		Bottom Wall Part	0	0%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	20	50%
	Window Bar	14	8%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : -10, WEST : -10 Other End - EAST : -8, WEST : -10
Start Date : 17-Jun-2019, Completion Date : 26-Jun-2019, Net Repair Days : 9, Total Man Hours : 822

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	S K SHARMA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
---------------------	----------------------	------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071027


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8	50%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : -6 Other End - EAST : 5, WEST : 3

Start Date : 02-Dec-2019, Completion Date : 07-Dec-2019, Net Repair Days : 6, Total Man Hours : 1599

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071037


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	9	56%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	9	56%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	32	80%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : -6 Other End - EAST : -4, WEST : -6
Start Date : 30-Nov-2019, Completion Date : 07-Dec-2019, Net Repair Days : 7, Total Man Hours : 1508

HAMANT JADAV - JE	M L KOLI - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071028


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Bright Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	10	63%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	10	63%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	40	23%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 2 Other End - EAST : 5, WEST : 5
Start Date : 29-Nov-2019, Completion Date : 07-Dec-2019, Net Repair Days : 8, Total Man Hours : 1617

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071041


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8.5	53%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8.5	53%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : 0 Other End - EAST : 0, WEST : 2

Start Date : 03-Dec-2019, Completion Date : 11-Dec-2019, Net Repair Days : 8, Total Man Hours : 1576

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06243


Type : WGSCN

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	12	75%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	12	75%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	46	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 5 Other End - EAST : 10, WEST : 10
Start Date : 27-Nov-2019, Completion Date : 05-Dec-2019, Net Repair Days : 8, Total Man Hours : 1776

K K DEHARIA - JE	ANASTA PRASAD - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	--------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06237


Type : WGSCN

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	8.5	53%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	8.5	53%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	20	50%		Window Bar	46	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 6, WEST : 5 Other End - EAST : 7, WEST : 4
Start Date : 28-Nov-2019, Completion Date : 05-Dec-2019, Net Repair Days : 7, Total Man Hours : 1732

HAMANT JADAV - JE	M L KOLI - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06259


Type : WGSCN

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Blue	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	5	31%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	32	80%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -9, WEST : -7 Other End - EAST : -7, WEST : -6
Start Date : 28-Nov-2019, Completion Date : 05-Dec-2019, Net Repair Days : 7, Total Man Hours : 1360

PANKAJ KU SINGH - JE	ALOK CHOUDHARY - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	---------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07237


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	12	75%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	12	75%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	100	54%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : -3 Other End - EAST : 2, WEST : 0
Start Date : 28-Nov-2019, Completion Date : 09-Dec-2019, Net Repair Days : 10, Total Man Hours : 2156

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06250


Type : WGSCN

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Blue	Centre Stiffner for Headstock	4	100%	Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	7.5	47%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	7.5	47%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	24	60%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : -5 Other End - EAST : -2, WEST : -6
Start Date : 02-Dec-2019, Completion Date : 07-Dec-2019, Net Repair Days : 6, Total Man Hours : 1488

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR051015


Type : GS

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	10.5	66%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	10.5	66%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 4, WEST : 5 Other End - EAST : -3, WEST : -4

Start Date : 02-Dec-2019, Completion Date : 07-Dec-2019, Net Repair Days : 6, Total Man Hours : 1736

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071017


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	9.5	59%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	9.5	59%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 8, WEST : 7 Other End - EAST : 7, WEST : 10

Start Date : 04-Dec-2019, Completion Date : 12-Dec-2019, Net Repair Days : 8, Total Man Hours : 1560

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-----------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR081031


Type : GS

Built Year : 2008

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8.5	53%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8.5	53%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 0 Other End - EAST : 0, WEST : 4
Start Date : 05-Dec-2019, Completion Date : 14-Dec-2019, Net Repair Days : 9, Total Man Hours : 1608

K K DEHARIA - JE	ANASTA PRASAD - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	--------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR051012


Type : GS

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Blue	Centre Stiffner for Headstock	4	100%	Light Blue	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	11	69%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	11	69%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 6, WEST : 3 Other End - EAST : -6, WEST : 0
Start Date : 17-Dec-2019, Completion Date : 28-Dec-2019, Net Repair Days : 11, Total Man Hours : 1568

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071035


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8	50%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 6, WEST : 5 Other End - EAST : 6, WEST : 6
Start Date : 18-Dec-2019, Completion Date : 01-Jan-2020, Net Repair Days : 13, Total Man Hours : 752

P N VISHWKARMA - SSE	T R LARRE - JE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	----------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07419


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	9	56%	Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	9	56%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	22	55%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 3, WEST : 2 Other End - EAST : 8, WEST : 10
Start Date : 18-Jul-2019, Completion Date : 27-Jul-2019, Net Repair Days : 9, Total Man Hours : 1376

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-----------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07205


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	8.5	53%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	8.5	53%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -8, WEST : -7 Other End - EAST : -4, WEST : 0
Start Date : 09-Jul-2019, Completion Date : 16-Jul-2019, Net Repair Days : 7, Total Man Hours : 1248

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06741


Type : GSLRD

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	16	100%	Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	9	47%		Window Bar	16	19%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 0 Other End - EAST : 0, WEST : 0
Start Date : 15-Jun-2019, Completion Date : 25-Jun-2019, Net Repair Days : 9, Total Man Hours : 1564

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06467


Type : GS

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8	50%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	58	33%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -5, WEST : -3 Other End - EAST : -2, WEST : -5
Start Date : 02-Apr-2019, Completion Date : 11-Apr-2019, Net Repair Days : 9, Total Man Hours : 1780

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06265


Type : WGSCN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	8	20%
	Window Bar	24	13%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -2, WEST : -3 Other End - EAST : -2, WEST : -5
Start Date : 05-Apr-2019, Completion Date : 15-Apr-2019, Net Repair Days : 9, Total Man Hours : 1032

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
--------------------	------------------	--------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05715


Type : GSLRD

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Bright Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	16	100%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	9	47%		Window Bar	14	17%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 3 Other End - EAST : -2, WEST : 5
Start Date : 26-Apr-2019, Completion Date : 11-May-2019, Net Repair Days : 14, Total Man Hours : 1808

K K DEHARIA - JE	ANASTA PRASAD - JE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	--------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06876


Type : WGCWNAC

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6.5	41%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		3%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -7, WEST : -5 Other End - EAST : -4, WEST : -4
Start Date : 17-May-2019, Completion Date : 28-May-2019, Net Repair Days : 10, Total Man Hours : 0

K K TRIPATHI - SSE	H R KANNOJE - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	-------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07109


Type : WGACCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Blue	Centre Stiffner for Headstock	4	100%	Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	9	56%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	9	56%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		6%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 5 Other End - EAST : 2, WEST : 6
Start Date : 09-May-2019, Completion Date : 24-May-2019, Net Repair Days : 14, Total Man Hours : 1376

HAMANT JADAV - JE	M L KOLI - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06236


Type : CN

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	7	44%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	7	44%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	40	22%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 5 Other End - EAST : 7, WEST : 5
Start Date : 02-May-2019, Completion Date : 10-May-2019, Net Repair Days : 8, Total Man Hours : 1076

HAMANT JADAV - JE	M L KOLI - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07418


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8	50%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 6, WEST : 8 Other End - EAST : 3, WEST : 4
Start Date : 08-May-2019, Completion Date : 16-May-2019, Net Repair Days : 8, Total Man Hours : 1464

K K DEHARIA - JE	ANASTA PRASAD - JE	ARUN SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	--------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05339


Type : CN

Built Year : 2005

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -10, WEST : -10 Other End - EAST : -10, WEST : -8
Start Date : 25-May-2019, Completion Date : 04-Jun-2019, Net Repair Days : 9, Total Man Hours : 1404

K K DEHARIA - JE	ANASTA PRASAD - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	--------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07209


Type : CN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Blue	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	4	25%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -4, WEST : -6 Other End - EAST : 5, WEST : 2
Start Date : 30-Apr-2019, Completion Date : 09-May-2019, Net Repair Days : 9, Total Man Hours : 940

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07108


Type : WGACCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	6.5	41%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		4%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 9, WEST : 10 Other End - EAST : 0, WEST : -2
Start Date : 07-Sep-2019, Completion Date : 16-Sep-2019, Net Repair Days : 8, Total Man Hours : 1040

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07234


Type : CN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	5.5	34%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5.5	34%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	40	22%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : -6 Other End - EAST : 6, WEST : 2
Start Date : 06-Sep-2019, Completion Date : 17-Sep-2019, Net Repair Days : 10, Total Man Hours : 1068

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07232


Type : CN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	7	44%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	7	44%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	40	22%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 6, WEST : 4 Other End - EAST : 0, WEST : 3
Start Date : 07-Sep-2019, Completion Date : 18-Sep-2019, Net Repair Days : 10, Total Man Hours : 1232

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05225


Type : WGSCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	24	60%		Window Bar	42	23%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 5 Other End - EAST : -3, WEST : -6
Start Date : 07-Sep-2019, Completion Date : 16-Sep-2019, Net Repair Days : 8, Total Man Hours : 1136

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06716


Type : GSRD

Built Year : 2006

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Blue	Centre Stiffner for Headstock	4	100%	Red	Floor Stiffner for Headstock	4	100%
Green	Aux. Head stock	4	100%	Orange	Sole Bar	5.5	34%	Light Blue	Draft Gear Bracket	2	100%
Purple	Trough floor	1	14%	Dark Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5.5	34%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	10	28%		Window Bar	20	12%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 5 Other End - EAST : 5, WEST : 2
Start Date : 06-Sep-2019, Completion Date : 12-Sep-2019, Net Repair Days : 6, Total Man Hours : 1040

PANKAJ KU SINGH - JE	ALOK CHOUDHARY - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	---------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06620


Type : WGSCZ

Built Year : 2006

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	8	50%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	42	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -5, WEST : -2 Other End - EAST : -3, WEST : -2

Start Date : 05-Sep-2019, Completion Date : 12-Sep-2019, Net Repair Days : 7, Total Man Hours : 1328

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06766


Type : GSLRD

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	12	75%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	12	75%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	74%		Window Bar	20	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 2 Other End - EAST : 8, WEST : 10
Start Date : 05-Sep-2019, Completion Date : 12-Sep-2019, Net Repair Days : 7, Total Man Hours : 1607

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05262


Type : WGSCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	5.5	34%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5.5	34%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	40	22%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 0 Other End - EAST : 2, WEST : 4
Start Date : 04-Sep-2019, Completion Date : 11-Sep-2019, Net Repair Days : 7, Total Man Hours : 976

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05273


Type : WGSCN

Built Year : 2005

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	5	31%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	5	31%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	40	100%
	Window Bar	50	27%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	28	100%								

End Drooping: Rotary End - EAST : -6, WEST : -5 Other End - EAST : -10, WEST : -8
Start Date : 23-Jul-2019, Completion Date : 30-Jul-2019, Net Repair Days : 7, Total Man Hours : 1256

PANKAJ KU SINGH - JE	ALOK CHOUDHARY - JE	T K PANJA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
----------------------	---------------------	-----------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06881


Type : WGCWNAC

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4.5	28%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4.5	28%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		5%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 3, WEST : 6 Other End - EAST : 2, WEST : 0
Start Date : 11-Sep-2019, Completion Date : 23-Sep-2019, Net Repair Days : 11, Total Man Hours : 1056

U S BAJPAI - SSE	P N VISHWKARMA - SSE	V N GANVIR - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05461


Type : GS

Built Year : 2005

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6.5	41%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	46	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 0 Other End - EAST : -5, WEST : -2
Start Date : 15-Oct-2019, Completion Date : 23-Oct-2019, Net Repair Days : 8, Total Man Hours : 1072

K K TRIPATHI - SSE	H R KANNOJE - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	-------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05274


Type : WGSCN

Built Year : 2005

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	10	25%
	Window Bar	28	15%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -10, WEST : -4 Other End - EAST : -10, WEST : -6
Start Date : 07-Oct-2019, Completion Date : 16-Oct-2019, Net Repair Days : 9, Total Man Hours : 1139

K K DEHARIA - JE	ANASTA PRASAD - JE	S S SHIVHARE - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
------------------	--------------------	--------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06226


Type : WGSCN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	18	45%
	Window Bar	28	15%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : -6, WEST : -10 Other End - EAST : 0, WEST : 0
Start Date : 01-Oct-2019, Completion Date : 11-Oct-2019, Net Repair Days : 10, Total Man Hours : 1205

PANKAJ KU SINGH - JE	ALOK CHOUDHARY - JE	T K PANJA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
----------------------	---------------------	-----------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071015


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	7.5	47%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	7.5	47%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : -3 Other End - EAST : 2, WEST : -2
Start Date : 12-Dec-2019, Completion Date : 18-Dec-2019, Net Repair Days : 6, Total Man Hours : 1612

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06242


Type : WGSCN

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6	38%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	20	50%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 5 Other End - EAST : 0, WEST : 0
Start Date : 03-Dec-2019, Completion Date : 09-Dec-2019, Net Repair Days : 6, Total Man Hours : 1208

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-----------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07210


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	112	61%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 3, WEST : -5 Other End - EAST : 5, WEST : 0

Start Date : 09-Dec-2019, Completion Date : 14-Dec-2019, Net Repair Days : 6, Total Man Hours : 2236

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07422


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	8	50%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	46	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 6 Other End - EAST : 6, WEST : 4
Start Date : 20-Dec-2019, Completion Date : 01-Jan-2020, Net Repair Days : 11, Total Man Hours : 720

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06288


Type : WGSCN

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	11.5	72%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	11.5	72%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	34	85%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : -5 Other End - EAST : -6, WEST : -5
Start Date : 28-Nov-2019, Completion Date : 04-Dec-2019, Net Repair Days : 6, Total Man Hours : 1896

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07204


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Green	Centre Stiffner for Headstock	4	100%	Red	Floor Stiffner for Headstock	4	100%
Blue	Aux. Head stock	4	100%	Yellow	Sole Bar	5	31%	Blue	Draft Gear Bracket	2	100%
Red	Trough floor	2	29%	Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	40	22%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 3, WEST : 3 Other End - EAST : 10, WEST : 10
Start Date : 22-Nov-2019, Completion Date : 29-Nov-2019, Net Repair Days : 7, Total Man Hours : 1084

K K DEHARIA - JE	ANASTA PRASAD - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	--------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05257


Type : WGSCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6	38%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	48	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 0 Other End - EAST : -2, WEST : 0
Start Date : 07-Nov-2019, Completion Date : 16-Nov-2019, Net Repair Days : 9, Total Man Hours : 992

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07236


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	100	54%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 10 Other End - EAST : -6, WEST : -3
Start Date : 12-Dec-2019, Completion Date : 23-Dec-2019, Net Repair Days : 10, Total Man Hours : 1684

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05028


Type : WGFACCW

Built Year : 2005

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		9%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : -4 Other End - EAST : -2, WEST : -3
Start Date : 19-Nov-2019, Completion Date : 26-Nov-2019, Net Repair Days : 7, Total Man Hours : 1192

PANKAJ KU SINGH - JE	ALOK CHOUDHARY - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	---------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06703


Type : GSLRD

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	11.5	72%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	11.5	72%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	7	37%		Window Bar	18	21%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 3, WEST : 3 Other End - EAST : -3, WEST : -30
Start Date : 21-Nov-2019, Completion Date : 03-Dec-2019, Net Repair Days : 11, Total Man Hours : 1904

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071020


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6.5	41%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 0 Other End - EAST : -2, WEST : -5
Start Date : 16-Dec-2019, Completion Date : 23-Dec-2019, Net Repair Days : 7, Total Man Hours : 1840

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07416


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8	50%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	24	60%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -4, WEST : 0 Other End - EAST : -8, WEST : -8
Start Date : 23-Dec-2019, Completion Date : 01-Jan-2020, Net Repair Days : 9, Total Man Hours : 1150

T R LARRE - JE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------	----------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06625


Type : WGSCZ

Built Year : 2006

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	80	45%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : -2 Other End - EAST : 6, WEST : 8
Start Date : 20-Nov-2019, Completion Date : 02-Dec-2019, Net Repair Days : 11, Total Man Hours : 1763

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05473


Type : GS

Built Year : 2005

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	10	63%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	10	63%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 4, WEST : 0 Other End - EAST : 6, WEST : 5
Start Date : 23-Nov-2019, Completion Date : 03-Dec-2019, Net Repair Days : 9, Total Man Hours : 1604

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR071032


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	10	63%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	10	63%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	20	50%		Window Bar	48	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 4, WEST : -3 Other End - EAST : -4, WEST : -7
Start Date : 21-Dec-2019, Completion Date : 01-Jan-2020, Net Repair Days : 12, Total Man Hours : 875

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR05266


Type : WGSCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6	38%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	18	45%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 7 Other End - EAST : 7, WEST : 6
Start Date : 23-Dec-2019, Completion Date : 02-Jan-2020, Net Repair Days : 10, Total Man Hours : 538

K K DEHARIA - JE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07245


Type : WGSCN

Built Year : 2007

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	14	35%
	Window Bar	44	24%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : 3, WEST : 6 Other End - EAST : 4, WEST : 0
Start Date : 21-Dec-2019, Completion Date : 02-Jan-2020, Net Repair Days : 11, Total Man Hours : 912

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
-------------------	--------------------	------------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR06618


Type : GSCZ

Built Year : 2006

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	9	56%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	9	56%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	40	23%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 0 Other End - EAST : -8, WEST : -10
Start Date : 10-Oct-2019, Completion Date : 17-Oct-2019, Net Repair Days : 7, Total Man Hours : 1264

PANKAJ KU SINGH - JE	ALOK CHOUDHARY - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	---------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NR07402


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
 	Headstock Beam	2	100%	 	Centre Stiffner for Headstock	4	100%	 	Floor Stiffner for Headstock	4	100%
 	Aux. Head stock	4	100%	 	Sole Bar	6.5	41%	 	Draft Gear Bracket	2	100%
 	Trough floor	3	43%	 	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	22	55%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 4, WEST : 6 Other End - EAST : 2, WEST : 5
Start Date : 28-Dec-2019, Completion Date : 03-Jan-2020, Net Repair Days : 6, Total Man Hours : 784

K K TRIPATHI - SSE	H R KANNOJE - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	-------------------	------------------------	----------------------------	-------------------------