

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW05026


Type : WGFACCW

Built Year : 2005

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	5	31%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		4%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : -2 Other End - EAST : -3, WEST : -5
Start Date : 04-Apr-2019, Completion Date : 15-Apr-2019, Net Repair Days : 10, Total Man Hours : 1344

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-----------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW05707


Type : SLRD

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	12	75%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	12	75%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	19	100%		Window Bar	30	36%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 6, WEST : 0 Other End - EAST : 5, WEST : 0
Start Date : 10-May-2019, Completion Date : 27-May-2019, Net Repair Days : 15, Total Man Hours : 1760

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07422


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	8	50%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 10, WEST : 10 Other End - EAST : 10, WEST : 8
Start Date : 22-Jul-2019, Completion Date : 29-Jul-2019, Net Repair Days : 7, Total Man Hours : 1148

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW05129


Type : WGACCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4.5	28%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4.5	28%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		4%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 7, WEST : 0 Other End - EAST : 5, WEST : 0
Start Date : 18-Sep-2019, Completion Date : 23-Sep-2019, Net Repair Days : 5, Total Man Hours : 1173

M L KOLI - JE	HAMANT JADAV - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------	-------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07933


Type : GSRD

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	7	44%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	7	44%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	30	83%		Window Bar	42	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -8, WEST : -10 Other End - EAST : 0, WEST : 0
Start Date : 10-Oct-2019, Completion Date : 17-Oct-2019, Net Repair Days : 7, Total Man Hours : 1333

M L KOLI - JE	HAMANT JADAV - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------	-------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07440


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	67%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	20	50%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : 0 Other End - EAST : -6, WEST : -3
Start Date : 18-Oct-2019, Completion Date : 31-Oct-2019, Net Repair Days : 12, Total Man Hours : 1004

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07610


Type : WGSCZ

Built Year : 2007

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Centre Stiffner for Headstock	0	0%		Floor Stiffner for Headstock	0	0%
	Aux. Head stock	0	0%		Sole Bar	6.5	41%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Centre plate	0	0%		SoleBar Stiffner	4	67%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 4, WEST : 6 Other End - EAST : 2, WEST : 0
Start Date : 07-Dec-2019, Completion Date : 13-Dec-2019, Net Repair Days : 6, Total Man Hours : 1360

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06153


Type : WGSCZAC

Built Year : 2007

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	5	31%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		3%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -10, WEST : -9 Other End - EAST : -4, WEST : -4
Start Date : 01-Apr-2019, Completion Date : 09-Apr-2019, Net Repair Days : 8, Total Man Hours : 1232

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06202


Type : CN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Diagonal	4	100%		Logitudinal Channel Structure	0	0%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Bottom Wall Part	0	0%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	8	20%
	Window Bar	10	5%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : 0, WEST : 3 Other End - EAST : 5, WEST : 7
Start Date : 11-Apr-2019, Completion Date : 18-Apr-2019, Net Repair Days : 7, Total Man Hours : 656

M L KOLI - JE	HAMANT JADAV - JE	T K PANJA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
---------------	-------------------	-----------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW05706


Type : GSLRD

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	8	50%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	10	53%		Window Bar	16	19%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 5 Other End - EAST : -3, WEST : -5
Start Date : 01-Jun-2019, Completion Date : 11-Jun-2019, Net Repair Days : 9, Total Man Hours : 1416

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06210


Type : GSCN

Built Year : 2019

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Diagonal	4	100%		Logitudinal Channel Structure	0	0%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Bottom Wall Part	0	0%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	0	0%
	Window Bar	0	0%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : -7, WEST : -2 Other End - EAST : -6, WEST : -4
Start Date : 10-May-2019, Completion Date : 17-May-2019, Net Repair Days : 7, Total Man Hours : 568

HAMANT JADAV - JE	M L KOLI - JE	S K SHARMA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
-------------------	---------------	------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06205


Type : GSCN

Built Year : 2019

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Diagonal	4	100%		Logitudinal Channel Structure	0	0%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Bottom Wall Part	0	0%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	5	13%
	Window Bar	10	5%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : -8, WEST : -7 Other End - EAST : -4, WEST : -6
Start Date : 25-Apr-2019, Completion Date : 02-May-2019, Net Repair Days : 7, Total Man Hours : 0

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
-------------------	--------------------	------------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06203


Type : GSCN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Diagonal	4	100%		Logitudinal Channel Structure	0	0%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Bottom Wall Part	0	0%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	0	0%
	Window Bar	0	0%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : 0, WEST : -2 Other End - EAST : 0, WEST : 0
Start Date : 13-Apr-2019, Completion Date : 20-Apr-2019, Net Repair Days : 7, Total Man Hours : 644

K K DEHARIA - JE	ANASTA PRASAD - JE	S S SHIVHARE - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
------------------	--------------------	--------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07407


Type : GS

Built Year : 2007

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6	38%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : -6 Other End - EAST : -2, WEST : 5
Start Date : 08-May-2019, Completion Date : 16-May-2019, Net Repair Days : 8, Total Man Hours : 1204

M L KOLI - JE	HAMANT JADAV - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------	-------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW04708


Type : GSLRD

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	13	81%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	13	81%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	10	53%		Window Bar	20	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -8, WEST : -6 Other End - EAST : -6, WEST : -6
Start Date : 31-May-2019, Completion Date : 11-Jun-2019, Net Repair Days : 10, Total Man Hours : 1688

M L KOLI - JE	HAMANT JADAV - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------	-------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07932


Type : GSRD

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6	38%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	12	63%		Window Bar	18	21%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 4, WEST : 3 Other End - EAST : 0, WEST : -3
Start Date : 26-Aug-2019, Completion Date : 31-Aug-2019, Net Repair Days : 6, Total Man Hours : 1289

M L KOLI - JE	HAMANT JADAV - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------	-------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW05028


Type : WGFACCW

Built Year : 2005

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		2%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 4 Other End - EAST : 4, WEST : 3
Start Date : 20-Jun-2019, Completion Date : 29-Jun-2019, Net Repair Days : 9, Total Man Hours : 1144

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07916


Type : GSRD

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	5	31%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	19	48%		Window Bar	32	17%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 6, WEST : 8 Other End - EAST : -5, WEST : -4
Start Date : 30-Jul-2019, Completion Date : 06-Aug-2019, Net Repair Days : 7, Total Man Hours : 1266

HAMANT JADAV - JE	M L KOLI - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07431


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Blue	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Light Blue	Sole Bar	8	50%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	40	22%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -5, WEST : -3 Other End - EAST : 4, WEST : 0
Start Date : 11-Jul-2019, Completion Date : 20-Jul-2019, Net Repair Days : 9, Total Man Hours : 1336

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW04704


Type : SLRD

Built Year : 2005

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	14	88%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	0	0%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	14	88%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	9	47%		Window Bar	14	17%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : -6 Other End - EAST : -3, WEST : -4
Start Date : 04-May-2019, Completion Date : 10-May-2019, Net Repair Days : 6, Total Man Hours : 0

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW05279


Type : WGSCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4.5	28%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4.5	28%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 0 Other End - EAST : -8, WEST : -4
Start Date : 26-Jun-2019, Completion Date : 03-Jul-2019, Net Repair Days : 7, Total Man Hours : 1076

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW04713


Type : GSLRD

Built Year : 2004

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	0	0%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	8	42%		Window Bar	12	14%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 4 Other End - EAST : 0, WEST : 0
Start Date : 30-Apr-2019, Completion Date : 07-May-2019, Net Repair Days : 7, Total Man Hours : 1480

PANKAJ KU SINGH - JE	ALOK CHOUDHARY - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	---------------------	------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW05224


Type : CN

Built Year : 2005

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Diagonal	4	100%		Logitudinal Channel Structure	1	50%
	Aux. Head stock	0	0%		Sole Bar	2	13%		Draft Gear Bracket	0	0%
	Trough floor	2	40%		Bottom Wall Part	2	13%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	2	5%
	Window Bar	5	3%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	11	100%								

End Drooping: Rotary End - EAST : -5, WEST : -6 Other End - EAST : -3, WEST : -4
Start Date : 24-Apr-2019, Completion Date : 04-May-2019, Net Repair Days : 10, Total Man Hours : 0

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
------------------	----------------------	------------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06206


Type : WGSCN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Diagonal	4	100%		Logitudinal Channel Structure	0	0%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Bottom Wall Part	0	0%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	0	0%
	Window Bar	0	0%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : 2, WEST : 3 Other End - EAST : -4, WEST : -5
Start Date : 29-Apr-2019, Completion Date : 03-May-2019, Net Repair Days : 5, Total Man Hours : 584

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	ARUN SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
-----------------------	------------------	------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06204


Type : WGSCN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Diagonal	4	100%		Logitudinal Channel Structure	0	0%
	Aux. Head stock	0	0%		Sole Bar	2	13%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Bottom Wall Part	2	13%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	0	0%
	Window Bar	0	0%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	11	100%								

End Drooping: Rotary End - EAST : 2, WEST : 5 Other End - EAST : 7, WEST : 7
Start Date : 30-Apr-2019, Completion Date : 08-May-2019, Net Repair Days : 8, Total Man Hours : 600

HAMANT JADAV - JE	M L KOLI - JE	S K SHARMA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
-------------------	---------------	------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07249


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	5.5	34%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5.5	34%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	24	60%		Window Bar	40	22%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 0 Other End - EAST : 0, WEST : 0
Start Date : 19-Aug-2019, Completion Date : 26-Aug-2019, Net Repair Days : 7, Total Man Hours : 0

K K DEHARIA - JE	ANASTA PRASAD - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	--------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07204


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	5	31%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	22	55%		Window Bar	40	22%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 6, WEST : 6 Other End - EAST : -3, WEST : 6
Start Date : 20-Aug-2019, Completion Date : 24-Aug-2019, Net Repair Days : 5, Total Man Hours : 1088

U S BAJPAI - SSE	P N VISHWKARMA - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07229


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6	38%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	32	80%		Window Bar	48	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -5, WEST : -5 Other End - EAST : 4, WEST : 0
Start Date : 20-Dec-2019, Completion Date : 01-Jan-2020, Net Repair Days : 11, Total Man Hours : 1024

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07702


Type : GSLRD

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	14	88%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	14	88%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	7	37%		Window Bar	20	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 4, WEST : 6 Other End - EAST : -5, WEST : -3

Start Date : 16-Dec-2019, Completion Date : 24-Dec-2019, Net Repair Days : 8, Total Man Hours : 2182

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06208


Type : CN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Diagonal	4	100%		Logitudinal Channel Structure	0	0%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Bottom Wall Part	0	0%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	0	0%
	Window Bar	0	0%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : -6, WEST : -4 Other End - EAST : -7, WEST : -3
Start Date : 16-May-2019, Completion Date : 24-May-2019, Net Repair Days : 8, Total Man Hours : 584

HAMANT JADAV - JE	M L KOLI - JE	S K SHARMA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
-------------------	---------------	------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06207


Type : WGSCN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Diagonal	4	100%		Logitudinal Channel Structure	0	0%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Bottom Wall Part	0	0%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	10	25%
	Window Bar	18	10%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : -8, WEST : -6 Other End - EAST : -6, WEST : -8
Start Date : 10-Apr-2019, Completion Date : 16-Apr-2019, Net Repair Days : 6, Total Man Hours : 696

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
-------------------	--------------------	------------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07476


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Pink	Headstock Beam	2	100%	Dark Blue	Centre Stiffner for Headstock	4	100%	Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	5.5	34%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	5.5	34%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 10, WEST : 10 Other End - EAST : 7, WEST : 8
Start Date : 10-Sep-2019, Completion Date : 14-Sep-2019, Net Repair Days : 5, Total Man Hours : 1162

PANKAJ KU SINGH - JE	ALOK CHOUDHARY - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	---------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07425


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	5	31%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 6, WEST : 4 Other End - EAST : -3, WEST : -6
Start Date : 26-Jul-2019, Completion Date : 02-Aug-2019, Net Repair Days : 7, Total Man Hours : 1237

PANKAJ KU SINGH - JE	ALOK CHOUDHARY - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	---------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW05109


Type : WGACCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	6.5	41%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		4%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 10, WEST : 5 Other End - EAST : 10, WEST : 10
Start Date : 04-Sep-2019, Completion Date : 11-Sep-2019, Net Repair Days : 7, Total Man Hours : 1260

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06409


Type : GS

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Blue	Headstock Beam	2	100%	Green	Centre Stiffner for Headstock	4	100%	Red	Floor Stiffner for Headstock	4	100%
Black	Aux. Head stock	4	100%	Yellow	Sole Bar	5	31%	Light Blue	Draft Gear Bracket	2	100%
Orange	Trough floor	2	29%	Dark Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 0 Other End - EAST : 2, WEST : 0
Start Date : 09-Aug-2019, Completion Date : 17-Aug-2019, Net Repair Days : 8, Total Man Hours : 1368

M L KOLI - JE	HAMANT JADAV - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------	-------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07442


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	7	44%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	7	44%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	22	55%		Window Bar	42	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : 0 Other End - EAST : 0, WEST : 4

Start Date : 04-Sep-2019, Completion Date : 13-Sep-2019, Net Repair Days : 9, Total Man Hours : 1139

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07443


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	40	23%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : -3 Other End - EAST : 5, WEST : 4

Start Date : 18-Nov-2019, Completion Date : 23-Nov-2019, Net Repair Days : 6, Total Man Hours : 1075

HAMANT JADAV - JE	M L KOLI - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW96712


Type : SLR

Built Year : 1996

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	1	50%		Centre Stiffner for Headstock	2	50%		Floor Stiffner for Headstock	2	50%
	Aux. Head stock	2	50%		Sole Bar	0.5	3%		Draft Gear Bracket	1	50%
	Trough floor	0	0%		Centre plate	1	50%		SoleBar Stiffner	4	100%
	Bottom Wall Part	0.5	3%		Body panel/patch		20%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 0 Other End - EAST : 0, WEST : 0
Start Date : 15-Feb-2020, Completion Date : 24-Feb-2020, Net Repair Days : 8, Total Man Hours : 1144

K K TRIPATHI - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	MANOJ AGARAWAL - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	------------------------	-----------------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW05714


Type : GSLRD

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	13	81%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	13	81%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	10	53%		Window Bar	14	17%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -3, WEST : 6 Other End - EAST : 0, WEST : 4

Start Date : 01-Nov-2019, Completion Date : 08-Nov-2019, Net Repair Days : 7, Total Man Hours : 1508

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06151


Type : WGSCZAC

Built Year : 2006

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Blue	Centre Stiffner for Headstock	4	100%	Red	Floor Stiffner for Headstock	4	100%
Green	Aux. Head stock	4	100%	Yellow	Sole Bar	4	25%	Blue	Draft Gear Bracket	2	100%
Red	Trough floor	2	29%	Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : -3 Other End - EAST : -4, WEST : -3
Start Date : 11-Nov-2019, Completion Date : 20-Nov-2019, Net Repair Days : 9, Total Man Hours : 980

K K TRIPATHI - SSE	H R KANNOJE - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	-------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07452


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	5	31%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	44	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 4 Other End - EAST : -3, WEST : -5
Start Date : 06-Dec-2019, Completion Date : 12-Dec-2019, Net Repair Days : 6, Total Man Hours : 1561

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07208


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Green	Centre Stiffner for Headstock	4	100%	Red	Floor Stiffner for Headstock	4	100%
Blue	Aux. Head stock	4	100%	Yellow	Sole Bar	4	25%	Blue	Draft Gear Bracket	2	100%
Red	Trough floor	2	29%	Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	44	24%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 10 Other End - EAST : 9, WEST : 8
Start Date : 16-Nov-2019, Completion Date : 23-Nov-2019, Net Repair Days : 7, Total Man Hours : 880

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06209


Type : WGSCN

Built Year : 2006

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	0	0%		Diagonal	4	100%		Logitudinal Channel Structure	0	0%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	0	0%		Bottom Wall Part	0	0%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	14	35%
	Window Bar	20	11%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : -2, WEST : -3 Other End - EAST : -3, WEST : -4
Start Date : 08-Nov-2019, Completion Date : 14-Nov-2019, Net Repair Days : 6, Total Man Hours : 948

K K TRIPATHI - SSE	H R KANNOJE - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
--------------------	-------------------	------------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07201


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	21	53%		Window Bar	46	25%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 6, WEST : 0 Other End - EAST : 5, WEST : 0
Start Date : 08-Nov-2019, Completion Date : 16-Nov-2019, Net Repair Days : 8, Total Man Hours : 928

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07207


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : -5 Other End - EAST : 5, WEST : 5
Start Date : 18-Nov-2019, Completion Date : 27-Nov-2019, Net Repair Days : 9, Total Man Hours : 1094

H R KANNOJE - SSE	K K TRIPATHI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	--------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07608


Type : WGSCZ

Built Year : 2007

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	5	31%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	5	83%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	46	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 3, WEST : 2 Other End - EAST : 2, WEST : 0
Start Date : 23-Nov-2019, Completion Date : 30-Nov-2019, Net Repair Days : 7, Total Man Hours : 1192

M L KOLI - JE	HAMANT JADAV - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------	-------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06407


Type : GS

Built Year : 2006

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	27%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -4, WEST : 2 Other End - EAST : -2, WEST : 6
Start Date : 21-Nov-2019, Completion Date : 27-Nov-2019, Net Repair Days : 6, Total Man Hours : 1175

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07206


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	48	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 6, WEST : 0 Other End - EAST : 0, WEST : 3
Start Date : 08-Nov-2019, Completion Date : 16-Nov-2019, Net Repair Days : 8, Total Man Hours : 953

HAMANT JADAV - JE	M L KOLI - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07435


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	67%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	80	45%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 3, WEST : 0 Other End - EAST : -2, WEST : -2
Start Date : 14-Nov-2019, Completion Date : 22-Nov-2019, Net Repair Days : 8, Total Man Hours : 944

K K TRIPATHI - SSE	H R KANNOJE - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	-------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW05701


Type : GSLRD

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	11	69%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	11	69%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	10	53%		Window Bar	16	19%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -4, WEST : 0 Other End - EAST : 0, WEST : 2

Start Date : 15-Nov-2019, Completion Date : 21-Nov-2019, Net Repair Days : 6, Total Man Hours : 1618

HAMANT JADAV - JE	M L KOLI - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07212


Type : WGSCN

Built Year : 2007

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Diagonal	4	100%		Logitudinal Channel Structure	2	100%
	Aux. Head stock	2	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	40%		Bottom Wall Part	4	25%		Body panel/patch		100%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	20	50%
	Window Bar	40	22%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	22	100%								

End Drooping: Rotary End - EAST : 5, WEST : 7 Other End - EAST : -3, WEST : -8
Start Date : 12-Oct-2019, Completion Date : 21-Oct-2019, Net Repair Days : 8, Total Man Hours : 1078

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
--------------------	------------------	--------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07437


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	8	50%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	8	50%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	24	60%		Window Bar	40	23%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 5 Other End - EAST : -4, WEST : -3

Start Date : 04-Oct-2019, Completion Date : 15-Oct-2019, Net Repair Days : 10, Total Man Hours : 1168

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-----------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW04266


Type : WGSCN

Built Year : 2004

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Green	Centre Stiffner for Headstock	4	100%	Red	Floor Stiffner for Headstock	4	100%
Blue	Aux. Head stock	4	100%	Orange	Sole Bar	4	25%	Purple	Draft Gear Bracket	2	100%
Black	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	14	35%		Window Bar	34	18%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -10, WEST : -10 Other End - EAST : -6, WEST : -7
Start Date : 04-Oct-2019, Completion Date : 15-Oct-2019, Net Repair Days : 10, Total Man Hours : 1216

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07203


Type : WGSCN

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4.5	28%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	4.5	28%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	42	23%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -4, WEST : -3 Other End - EAST : 2, WEST : 0
Start Date : 28-Sep-2019, Completion Date : 05-Oct-2019, Net Repair Days : 7, Total Man Hours : 1216

ANASTA PRASAD - JE	K K DEHARIA - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW05702


Type : GSLRD

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	6	38%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	10	53%		Window Bar	18	21%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -10, WEST : -10 Other End - EAST : 7, WEST : 2
Start Date : 18-Oct-2019, Completion Date : 24-Oct-2019, Net Repair Days : 6, Total Man Hours : 1420

HAMANT JADAV - JE	M L KOLI - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07438


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4	25%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	67%
	Bottom Wall Part	4	25%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	28	70%		Window Bar	40	23%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -2, WEST : 0 Other End - EAST : -3, WEST : -5
Start Date : 02-Nov-2019, Completion Date : 09-Nov-2019, Net Repair Days : 7, Total Man Hours : 862

P N VISHWKARMA - SSE	U S BAJPAI - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07436


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	4.5	28%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	5	83%
	Bottom Wall Part	4.5	28%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	26	65%		Window Bar	46	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -8, WEST : -5 Other End - EAST : -6, WEST : -8
Start Date : 14-Oct-2019, Completion Date : 19-Oct-2019, Net Repair Days : 6, Total Man Hours : 1192

HAMANT JADAV - JE	M L KOLI - JE	T K PANJA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-------------------	---------------	-----------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW06216


Type : WGSCN

Built Year : 2006

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	7.5	47%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	7.5	47%		Body panel/patch		100%		Door Top/Roof Patch		100%
	Window Module		0%		Window Sill	20	50%		Window Bar	40	22%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -6, WEST : 2 Other End - EAST : -10, WEST : -10
Start Date : 05-Oct-2019, Completion Date : 17-Oct-2019, Net Repair Days : 11, Total Man Hours : 1259

R KU KHARE - SSE	MAYANK PRAJAPATI - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	-----------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07931


Type : GSRD

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6.5	41%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	22	61%		Window Bar	44	26%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -10, WEST : -9 Other End - EAST : -3, WEST : -4
Start Date : 12-Oct-2019, Completion Date : 21-Oct-2019, Net Repair Days : 8, Total Man Hours : 1240

K K DEHARIA - JE	ANASTA PRASAD - JE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
------------------	--------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW05277


Type : WGSCN

Built Year : 2005

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	6	38%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	24	60%		Window Bar	40	22%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : -8, WEST : -4 Other End - EAST : -6, WEST : -3
Start Date : 15-Oct-2019, Completion Date : 22-Oct-2019, Net Repair Days : 7, Total Man Hours : 998

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	S S SHIVHARE - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
-----------------------	------------------	--------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07601


Type : WGSCZ

Built Year : 2007

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6.5	41%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	6.5	41%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	60	34%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 5, WEST : 3 Other End - EAST : -2, WEST : -2
Start Date : 17-Oct-2019, Completion Date : 25-Oct-2019, Net Repair Days : 8, Total Man Hours : 1384

K K TRIPATHI - SSE	H R KANNOJE - SSE	OM PRAKASH SINGH - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	-------------------	------------------------	----------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW96429


Type : GS

Built Year : 1996

Make : BEML

Form No. F/BR/BEML/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	1	50%		Diagonal	4	100%		Logitudinal Channel Structure	1	50%
	Aux. Head stock	0	0%		Sole Bar	0	0%		Draft Gear Bracket	0	0%
	Trough floor	4	80%		Bottom Wall Part	0	0%		Body panel/patch		30%
	Door Top/Roof Patch		0%		Seat Bracket Rail		0%		Window Sill	0	0%
	Window Bar	0	0%		Seat pillar/lav. Partition		100%		UIC end construction		0%
	Body Pillar Part	0	100%								

End Drooping: Rotary End - EAST : 0, WEST : 0 Other End - EAST : 0, WEST : 0
Start Date : 12-Feb-2020, Completion Date : 21-Feb-2020, Net Repair Days : 9, Total Man Hours : 0

HAMANT JADAV - JE	PANKAJ DAMARE - JE	S K SHARMA - SSE	V N GANVIR - SSE	Verified By:QU-Incharge
-------------------	--------------------	------------------	------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :NW07421


Type : GS

Built Year : 2007

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	6	38%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	6	38%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	50	28%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 3, WEST : -2 Other End - EAST : -4, WEST : -4
Start Date : 21-May-2019, Completion Date : 29-May-2019, Net Repair Days : 8, Total Man Hours : 1100

PANKAJ KU SINGH - JE	ALOK CHOUDHARY - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
----------------------	---------------------	------------------	----------------------------	-------------------------