

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :CR07607


Type : GSCZ

Built Year : 2007

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



**Rotary Side**

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	7	18%		Window Bar	15	8%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : 2 Other End - EAST : -2, WEST : -2  
Start Date : 18-Apr-2019, Completion Date : 26-Apr-2019, Net Repair Days : 8, Total Man Hours : 1664

ALOK CHOUDHARY - JE	PANKAJ KU SINGH - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
---------------------	----------------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. : CR94453


Type : GS

Built Year : 1994

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	5.5	34%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	5.5	34%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 0 Other End - EAST : 0, WEST : 0  
Start Date : 14-Feb-2020, Completion Date : 22-Feb-2020, Net Repair Days : 8, Total Man Hours : 0

PANKAJ DAMARE - JE	HAMANT JADAV - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------	-------------------	------------------	----------------------------	-------------------------

# Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)  
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :CR94640


Type : WGSCZ

Built Year : 1994

Make : RCF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	1	50%		Centre Stiffner for Headstock	2	50%		Floor Stiffner for Headstock	2	50%
	Aux. Head stock	2	50%		Sole Bar	2	13%		Draft Gear Bracket	1	50%
	Trough floor	2	29%		Centre plate	1	50%		SoleBar Stiffner	4	100%
	Bottom Wall Part	2	13%		Body panel/patch		30%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 0, WEST : 0 Other End - EAST : 0, WEST : 0  
Start Date : 06-Feb-2020, Completion Date : 14-Feb-2020, Net Repair Days : 8, Total Man Hours : 0

MOHD. JAFER QURASHI - JE	ANASTA PRASAD - JE	S K SHARMA - SSE	V N GANVIR - SSE In-charge	Verified By:QU-Incharge
--------------------------	--------------------	------------------	----------------------------	-------------------------