

**Dy. CMM/CRWS/BHOPAL**

No. 68.14-WB-04

Date : 22.04.2014

Tender to be closed on... **29.04..2014..... at 14:30 Hrs .**

Place of Delivery : Dy. CMM (CRWS) BPL {AT MAIN STORES}

Delivery Terms : 30 Days / Ex stock

**Note** : **Rates should be quoted in words as well as in figures also.**

Sr	Tender No	Description	Qty
1	<u>68.14.5074</u>	M.S. Back pannel, size 740 x 625 x 1.6 MM thick material, as per IS: 2062-2006, E-250 CUC duly with one coat of Red Oxide Primer to IS:2074-93.	300 Nos.
2	<u>68.04.5225</u>	Ventilator (Tra type in side) as per Drg. No. CRW/SK-817 Alt.-01.	400 Nos.
3.	<u>68.14.5305</u>	Set of Bearing for Industrial vehicles. One set consisting as per enclosed annexure, Make SKF/FAG/NBC. proof of purchase from OEM / dealer to be submitted with supply.	01 Set.
4	68.14.5304	Set of spares for TATA truck model 1613 TC. One set consisting as per enclosed annexure.	<u>01 Set.</u>
5	68.14.5110	Sealed window glass unit for Body side window of AC chair car to drawing no. ICF Drawing ICF/SK-5-4-021 alt ' nil' .As per ICF Drawing no. ICF/SK-5-4-021 alt' nil' ICF Drawing no. ICF/SK-5-4-021 alt' nil'.	32 Nos.
6	68.14.5309	ESAB make pressure arm code no. 1651689006 for wire feeder of two roll drive of ESAB make Auto K-400 Co2 machine (OEM certificate required at the time of supply)	30 Nos
7	68.14.5310	ESAB make Roller 'V' groove 0.8 / 1.2 mm code no. 1651687161 for two roll drive system of ESAB make Auto K-400 Co2 machine (OEM certificate required at the time of supply)	40 Nos
8	68.14.5311	ESAB make pressure device code no. 1651689005 for wire feeder of ESAB make Auto K-400 Co2 machine (OEM certificate required at the time of supply)	30 Nos
9	68.14.5798	MCB (Three Pole) 80 Amps.'C'Curve, suitable for inductive load, Item Code-TTPC-80 of HPL make,240/415 volts A.C.,50 HZ,Breaking capacity 10 KA, Make GE/ Havells / L&T / MDS / SIEMENS / INDO ASIAN / CGL / HPL. / C & S / STANDARD.	18 Nos

Annexure 68.14.5304 due on 29.04.14

Sr.	Description	Qty	Make
01.	Fly wheel assembly	01 No	Telco / Luck / CA / Gajra
02.	Pressure plate assembly	02 Nos	Telco / Luck / CA
03.	Clutch plate assembly	04 Nos	Telco / Luck / CA
04.	Clutch cylinder assembly	02 Nos	Telco / TVS / KBS
05.	Slave cylinder assembly	02 Nos	Telco / TVS / KBS
06.	Fan Belt No. 980	02 Nso	Telco / Mico / Fenner
07.	Fan Belt No. 1325	04 Nos	Telco / Mico / Fenner

Annexure 68.14.5305 due on 29.04.14

Sr. No.	Description	Qty
01.	Cyl. Roller bearing no. 208	12 Nos
02.	Taper Roller bearing no. 30209	12 Nos
03.	Self Aligning Ball bearing no. 1207	12 Nos
04.	Taper Roller bearing no. 32308	05 Nos
05.	Taper Roller bearing no. 32208	05 Nos

Cmm/CRWS/BPL

Dy

ID : [dycmmpps@gmail.com](mailto:dycmmpps@gmail.com)