

Dy. CMM/CRWS/BHOPAL

No. 68.14-WB-23

Date : 05.11.2014.

Tender to be closed on... **11.11.2014..... at 14:30 Hrs.**

Place of Delivery : Dy. CMM (CRWS) BPL {AT MAIN STORES}

Delivery Terms : 30 Days / Ex stock

Note : Rates should be quoted in words as well as in figures also.

| Sr | Tender No | Description | Qty |
|----|------------|--|-------------|
| 1 | 68.14.5778 | Safety Goggles, Ultra soft flexible, poly carbonate lens with scratch resistant hard coating, protection against flying object, dust and chemical splash, product no. 1621 of 3M India Ltd. or equivalent make of smith & wesson or of peltor, along with OEM test & warranty certificate as per technical specification attached as Annexure-I. | 350 Nos. |
| 2 | 68.14.5779 | Eye for pad Lock for B.S. Door of ICF & BEML Coaches. As per Drg. NO. CRW/SK-415, Item No.-3 to IS:1079. | 2000 Nos. |
| 3 | 68.14.5747 | Set of spares for Godrej make Fork Lift. One set consisting water pump Assbly as per Godrej Part No. MH 02554348= 02 Nos, seat assembly as per Godrej Part No. MH 02354927 = 03 Nos and Rubber cushion Godrej Part No. MH 02354240= 12 Nos Make- Godrej or Similar. | 01 Sets. |
| 4 | 68.14.5748 | Cabin Fan without Regulator 300mm. 90 watt, 2300 RMP, 50 Hz, 230 Volt, AC. Khaitan make model-Paloma or similar modal Make- Bajaj & Crompton Greaves. | 06 Nos. |
| 5 | 68.14.5749 | Brass Adopter for connections of single stage regulators at outlet points as per sample. | 50 Nos. |
| 6 | 68.14.5781 | Hex Head M-8 x 35 MM steel full thread to IS:1363 part-II with 01 nut M-8 to IS:1363 part-III bright zinc plated to be supplied in assembled condition. | 30,000 Nos. |
| 7 | 68.14.5782 | Fixture for Battery Box Frame of AC coaches, drg no. CRWS/BPL/EL/SK/2014-05 (Sample should be got approved before bulk supply) | 01 No. |

T. No. 68.14.5778. Annexure - I Specification :

1. Safety Goggles, splash proof, protection against flying object, dust and chemical splash, front side type having polycarbonate lenses in vinyle frame with minimum four indirect vents.
2. Lenses should offer minimum 99% UV protection.
3. Should comply high velocity impact test, high mass impact test, minimum thickness & penetration test as per ASNI Z 87.1 (Certificate required)
4. Supplier should provide MSDS, warranty certificate & above certificate from the OEM.
5. The supplier must give extensive training program on usage, maintenance & upkeep of the respirator.
6. The supplier or the OEM must have after sales service support for the continuous & effective troubleshot.

Dy.CMM/CRWS/BPL**ID : dycmmpps@gmail.com**