





- 2.10 No claim whatsoever will be given to the supplier in any circumstances.
- 2.11 Material for making the seats and berths shall be procured from the approved sources advised by RDSO as valid on date of opening of tender. Suppliers are advised to refer the latest RDSO vendor list for the current approved source of supply.
- 2.12 Vendor approvals shall be confirmed, on date of inspection of raw material, by RITES.
- 2.13 The scope of Supply of material mentioned of this STR no. CRWS/BPL/GSCN/cushion mtrl / STR003, ver 07 Dt. 12.06.2015, Para 3.0, note (i), (ii) & (iii) to be ensured before supply.

**3.0 SCOPE OF SUPPLY OF MATERIAL FOR GSCN COACHES**

The details of seat & berths required for one GSCN coach is given below. Following materials are to be supplied by the firm in a coach set . Descriptions, Drawing numbers. and required quantity are as under: -

**Table ( A ) : For RCF wider way type coaches :**

S.No.	Description	Drg. No.	Qty per set
1.	Transverse seat Complete for SCN coaches	SE 61361 alt 'c', Frame to drawing no. SE 61362 alt 'nil'	18 nos.
2.	Transverse Middle berth complete for SCN coaches.	SE 61365 alt 'c', Frame to drawing no. SE 61366 alt 'a'	18 nos.
3.	Transverse Upper berth & Longitudinal Upper berth complete for SCN coaches.	SE 61365 alt 'c', Frame to drawing no. SE 61366 alt 'a'	27 nos.
4.	Single seat Complete for SCN coaches	SE 61363 alt 'c', Frame to drawing no. SE 61364 alt 'nil'	18 nos.
5.	Back rest cum Berth (Long) Complete for SCN coaches	SE 61371 alt 'c', Frame to drawing no. SE 61372 alt 'nil'	09 nos.
6.	Back rest cum Berth (Short) Complete for SCN coaches	SE 61373 alt 'b', Frame to drawing no. SE 61374 alt 'nil'	09 nos.
7.	Slotted CSK head screw M10x 25	As per IS: 1365/1978	54 nos.
<b>Total number of item in one coach set</b>			<b>153 Nos.</b>

Prepared by		Verified & Checked by	Approved by
 12/6/15 SSE/ Carpentry	 S SE/Furnishing	availability dng Chello-aly  J.E. Drawing	 13/7/15 QU Incharge