

Office of the DyCE(TM)/BPL
TENDER UNDER FINALISATION (Dy.CE/TM/BPL)

Jan,16											
S.N.	Name of work	NIT No.	Value of tender in Rs.	Stage of Tender						Remark	File NO,
				Briefing note and comparative statement	Vetting of Briefing Note	Tender Committee minutes finalised	Tender Committee minutes acceptance	Acceptance letter issued			
				Yes/No	Yes/No	Yes/No	Yes/No	Yes/No			
1	Hdraulic hose required for track machines. Make- Superseal, Parker, Aeroquip. Part No.EN-853-2SN10/SAE 100R2AT/No-6	BPL/W/TM/2015-16/29/09 dtd.11.09.15	59063	Yes	Yes	No	No	No	TC to be done	15/155	
2	Coupling required for pump drive of BCM machine working in WCR.	BPL/W/TM/2015-16/29/09 dtd.11.09.15	361239/-	Yes	Yes	No	No	No	TC to be done	14/0146	
3	Tamping tyne (small) required for UNI-4S-8410 machine.	BPL/W/TM/2015-16/30/10 dtd.11.09.15	132888/-	Yes	Yes	No	No	No	TC to be done	15/0054	
4	Pneumatic cylinder required for track machines.	BPL/W/TM/2015-16/30/10 dtd.11.09.15	88059/-	Yes	Yes	No	No	No	TC to be done	15/0122	
5	Pneumatic valves required for UTV machines. Make:- Phooltas or equivalent.	BPL/W/TM/2015-16/30/10 dtd.11.09.15	98112	Yes	Yes	No	No	No	TC to be done	15/0125	
6	Hydraulic oil required for mobile bridge inspection unit. Make:- IOCL, HPCL, BPCL. Part No. HLP 46	BPL/W/TM/2015-16/30/10 dtd.11.09.15	89876	Yes	Yes	No	No	No	TC to be done	15/159	
7	Tamping tyne required for tamping express machines.	BPL/W/TM/2015-16/31/11 dtd. 11.09.15	91678/-	Yes	Yes	No	No	No	TC to be done	15/0079	

8	Rocker bearing required for track machines	BPL/W/TM/2015-16/31/11 dtd. 11.09.15	46596/-	Yes	Yes	No	No	No	TC to be done	15/0074
9	Engine filter required for T-28 machines.	BPL/W/TM/2015-16/31/11 dtd. 11.09.15	92516/-	Yes	Yes	No	No	No	TC to be done	15/0080
10	Hydraulic filters required for T-28 machines.	BPL/W/TM/2015-16/31/11 dtd. 11.09.15	87203/-	Yes	Yes	No	No	No	TC to be done	15/0082
11	Seal ring required for rail wheel of T-28 machines.	BPL/W/TM/2015-16/31/11 dtd. 11.09.15	91760/-	Yes	Yes	No	No	No	TC to be done	15/0084
12	Distributor conveyor belt required for BCM-353 & BCM- 395 machines.	BPL/W/TM/2015-16/31/11 dtd. 11.09.15	99569/-	Yes	Yes	No	No	No	TC to be done	15/0085
13	Pneumatic sparesrequired for track machines.	BPL/W/TM/2015-16/31/11 dtd. 11.09.15	84282/-	Yes	Yes	No	No	No	TC to be done	15/0086
14	Hydraulic hoses required for track machines.	BPL/W/TM/2015-16/31/11 dtd. 11.09.15	83207/-	Yes	Yes	No	No	No	TC to be done	15/0100
15	Poly acetel sheet required for BCM machines.	BPL/W/TM/2015-16/31/11 dtd. 11.09.15	87120/-	Yes	Yes	No	No	No	TC to be done	15/0104
16	Pneumatic spares required for track machines.	BPL/W/TM/2015-16/31/11 dtd. 11.09.15	56301/-	Yes	Yes	No	No	No	TC to be done	15/0106
17	Hydraulic hoses required for TEXP-3959 machines during IOH.	BPL/W/TM/2015-16/31/11 dtd. 11.09.15	89999/-	Yes	Yes	No	No	No	TC to be done	15/0105
18	Valve required for CSM-959 machine.	15-16/106/99 dtd.09.11.15	98429/-	Yes	Yes	No	No	No	TC to be done	15/0241
19	Lub oil bypass filter required for Cummins engine of track machines.	15-16/119/112 dtd. 09.11.15	92508/-	Yes	Yes	No	No	No	TC to be done	15/243
20	Air cleaner filter required for track machines.	15-16/124/117 dtd.30.11.15	85253/-	Yes	Yes	No	No	No	TC to be done	15/0258
21	Spares required for Duetz engine of BCM machines.	15-16/130/123 dtd.30.11.15	141245	Yes	Yes	No	No	No	TC to be done	15/185
22	Spares required for Duetz engine of BCM machines.	15-16/131/124 dtd.30.11.15	128787	Yes	Yes	No	No	No	TC to be done	15/191
23	Colent required for track machine	15-16/137/130 dtd.04.12.15	93847	Yes	Yes	No	No	No	TC to be done	15/271
24	Spares required for repairing of moom TBD 232 V12 engine of track machine	15-16/139/132 dtd.04.12.15	92931	Yes	Yes	No	No	No	TC to be done	15/0277
25	Spares required for repairing of moom TBD 232 V12 engine of track machine	15-16/138/131 dtd. 04.12.15	74315	Yes	Yes	No	No	No	TC to be done	15/0276

26	Cross sliding cylinder required for T-28/804 machine.	BPL/W/TM/2015-16/15/35 dtd.29.10.15	565503/-	Yes	Yes	No	No	No	TC to be done	14/059
27	Thrust plate required for BCM Machine.	BPL/W/TM/2015-16/15/35 dtd.29.10.15	482119/-	Yes	Yes	No	No	No	TC to be done	14/113
28	Shaft required for lifting of BCM machines working in WCR	BPL/W/TM/2015-16/15/35 dtd.29.10.15	254205/-	Yes	Yes	No	No	No	TC to be done	14/138
29	Clutch gear wheel required for pinion shaft assembly of BCM machine working in WCR	BPL/W/TM/2015-16/15/35 dtd.29.10.15	645209/-	Yes	Yes	No	No	No	TC to be done	14/0170
30	Hydraulic motor required for BCM Machine	BPL/W/TM/2015-16/15/35 dtd.29.10.15	715826/-	Yes	Yes	No	No	No	TC to be done	14/144
31	PCB required for track machine	15-16/140/133 dtd.07.12.15	338091	Yes	Yes	No	No	No	TC to be done	15/092
32	Printed circuit board required for Track Machine	15-16/141/134 dtd.07.12.15	317601	Yes	Yes	No	No	No	TC to be done	15/0151
33	Safety valve required for track machine	15-16/142/135 dtd.07.12.15	145061	Yes	Yes	No	No	No	TC to be done	15/0215
34	Voltmeter & Ampermeter required for track machine	15-16/145/138 dtd.07.12.15	118117	Yes	Yes	No	No	No	TC to be done	15/0226
35	Seal set required for track machine.	15-16/146/139 dtd.07.12.15	135207	Yes	Yes	No	No	No	TC to be done	15/0227
36	Spasres required for track machine	15-16/147/140 dtd.07.12.15	131470	Yes	Yes	No	No	No	TC to be done	15/0239
37	Cylinder required for track machine	15-16/148/141 dt.07.12.15	138017	Yes	Yes	No	No	No	TC to be done	15/0252
38	ZF filter required for track machine	15-16/149/142 dtd.07.12.15	93922	Yes	Yes	No	No	No	TC to be done	15/0269
39	Pneumatic cylinder required for track machine	15-16/144/137 dtd.07.12.15	90906	Yes	Yes	No	No	No	TC to be done	15/0273
40	Rubber seal (3.5 mtr.) required for track machine	15-16/143/136 dtd.07.12.15	98826	Yes	Yes	No	No	No	TC to be done	15/0274
41	Wear plate required for BCM machines.	BPL/W/TM/2015-16/16/36 dtd.06.11.15	738303	Yes	Yes	No	No	No	TC to be done	13/0059
42	Hydraulic motor required for Unimat machines. Make- Veljan Denison. Part No.T2SC-022-2R01.A2.INR.	BPL/W/TM/2015-16/16/36 dtd.06.11.15	65858	Yes	Yes	No	No	No	TC to be done	15/146
43	Air compressor required for MWM engine of CSM 924 & UNI 8268 machine.	BPL/W/TM/2015-16/16/36 dtd.06.11.15	77179/-	Yes	Yes	No	No	No	TC to be done	14/271
44	Motor required for vibration unit of CSM/ Duomatic machines. Make:- Veljan, Denision.	BPL/W/TM/2015-16/16/36 dtd.06.11.15	79002/-	Yes	Yes	No	No	No	TC to be done	15/143

45	Radiator assly required for MWM engine provoded on CSM-924 machine.	BPL/W/TM/2015-16/16/36 dtd.06.11.15	481183	Yes	Yes	No	No	No	TC to be done	15/132
46	Relay required for track machine working in WCR.	BPL/W/TM/2015-16/16/36 dtd.06.11.15	70358/-	Yes	Yes	No	No	No	TC to be done	15/050
47	Spares required for T-28 machine. Make:-Ameca or equivalent	BPL/W/TM/2015-16/16/36 dtd.06.11.15	120750/-	Yes	Yes	No	No	No	TC to be done	15/187
48	Spares required for T-28 machine. Make:-Ameca or equivalent	BPL/W/TM/2015-16/16/36 dtd.06.11.15	137230/-	Yes	Yes	No	No	No	TC to be done	15/188
49	Spares required for UTV machines. Make:- Phooltas or equivalent	BPL/W/TM/2015-16/16/36 dtd.06.11.15	92295/-	Yes	Yes	No	No	No	TC to be done	15/186
50	Recoupment of motors required for BCM machines.	BPL/W/TM/2015-16/16/36 dtd.06.11.15	474600/-	Yes	Yes	No	No	No	TC to be done	14/140

