

Office of the DyCE(TM)/BPL
TENDER UNDER FINALISATION (Dy.CE/TM/BPL)

April , 16											
S.N.	Name of work	NIT No.	Value of tender in Rs.	Stage of Tender						Remark	File NO,
				Briefing note and comparative statement	Vetting of Briefing Note	Tender Committee minutes finalised	Tender Committee minutes acceptance	Acceptance letter issued			
				Yes/No	Yes/No	Yes/No	Yes/No	Yes/No			
1	Repairing of wheel axle frame of DUO-8042 M/C	BPL/W/TM/2015-16/17/37 dtd.30.11.15	98500	Yes	Yes	No	No	No	Under accounts concurrence	15/229	
2	Painting of FRM-1892 & BRM-101 track machine	BPL/W/TM/2015-16/17/37 dtd.30.11.15	94910	Yes	Yes	No	No	No	Under accounts concurrence	15/251	
3	Overhauling & repairing of control panel box of BCM 319 machine at ZTMD BPL	BPL/W/TM/2015-16/17/37 dtd.30.11.15	64900	Yes	Yes	No	No	No	Under accounts concurrence	15/153	
4	Wheel cylinder required for T-28 track machine.	BPL/W/TM/2015-16/19/39 dtd. 17.12.15	154000	Yes	Yes	No	No	No	TC to be done	15/0058	
5	Phosphor bronze plate required for T-28 machines.	BPL/W/TM/2015-16/19/39 dtd. 17.12.15	120960	Yes	Yes	No	No	No	TC to be done	15/0221	
6	Fastener required for track machines.	BPL/W/TM/2015-16/19/39 dtd. 17.12.15	127530	Yes	Yes	No	No	No	TC to be done	15/0205	
7	Brake shoe required for track machine.	BPL/W/TM/2015-16/19/39 dtd. 17.12.15	119700	Yes	Yes	No	No	No	TC to be done	15/0206	
8	Switch required for track machine.	BPL/W/TM/2015-16/19/39 dtd. 17.12.15	138474	Yes	Yes	No	No	No	TC to be done	15/0208	
9	Lifting roller required for track machine.	BPL/W/TM/2015-16/19/39 dtd. 17.12.15	140680	Yes	Yes	No	No	No	TC to be done	15/0231	
10	Overhauling /Major attention of ATRT P811S machine in ZTMD/BPL	BPL/W/TM/2015-16/22/42 dtd.08.01.16	15166085	Yes	Yes	No	No	No	TC to be done	ATRTR/1	
11	Trolley wheel required for track machines.	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	123027	Yes	Yes	No	No	No	TC to be done	15/0233	
12	Lifting hook required for UNIMAT machines.	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	139991	Yes	Yes	No	No	No	TC to be done	15/0232	

13	Valve required for Plassermatic machines working in WCR.	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	224148	Yes	Yes	No	No	No	TC to be done	14/0149
14	Sapres required for repairing of drive pump for BCM machine.	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	299550	Yes	Yes	No	No	No	TC to be done	15/0057
15	Wheel support cylinder required for T-28 machines	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	119920	Yes	Yes	No	No	No	TC to be done	15/204
16	Accumulator required for track machine. Make:- HYDAC/Plasser or equivalent	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	95389	Yes	Yes	No	No	No	TC to be done	15/279
17	Cutting chain assembly with carbide bit required for BCM Machines.	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	4260060	Yes	Yes	No	No	No	TC to be done	15/0101
18	Pinion shaft required for clutch assembly of BCM machines working in	BPL/W/TM/2015-16/20/40 dtd. 29.12.15	773526	Yes	Yes	No	No	No	TC to be done	14/0151
19	Spares and rewiring of drive control panel box of B-5 & Junction box B-50 with testing and commissioning for CSM-924 m/c at ZTMD Bhopal	BPL/W/TM/2015-16/21/41 dtd. 30.12.15	143938	Yes	Yes	No	No	No	Under accounts concurrence	Rewiring CSM-924
20	Wear plate required for BCM Machine.	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	146348/-	Yes	Yes	No	No	No	TC to be done	15/99
21	Tamping tyne (BIG) required for UNIS 8410 machine. Part No. CU30.6820.BE. Make:- INDIGENOUS.	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	84168/-	Yes	Yes	No	No	No	TC to be done	15/51
22	Wire rope sling required for ZTMD, UTV & Track Machines. Make:- Usha Martin, Mahadev, Diamond.	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	60446/-	Yes	Yes	No	No	No	TC to be done	15/147
23	Roller Bearing required for track machine for track machine. Part No.UD62.2610P/NJP 2224MCY. MAKE:- SKF, FAG	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	131328/-	Yes	Yes	No	No	No	TC to be done	15/286
24	Hydraulic Hose required track machine. Make:- PARKER, AEROQUIP, SUPERSEAL	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	76790/-	Yes	Yes	No	No	No	TC to be done	15/287
25	Hydraulic Hose required track machine. Make:- PARKER, AEROQUIP, SUPERSEAL	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	117390/-	Yes	Yes	No	No	No	TC to be done	15/288
26	Cardon shaft required for track machine. Part No. KGV180.1250.110.80. Make:- Plasser or equivalent.	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	94500/-	Yes	Yes	No	No	No	TC to be done	15/289
27	Double Pump required for track machine. Make:- VELJON DENISON	BPL/W/TM/2015-16/23/43 dtd. 08.02.16	135842/-	Yes	Yes	No	No	No	TC to be done	15/249

28	Pinion for AXLE gear box of TRT machine. Make:- Phooltas or equivalent.	BPL/W/TM/2015-16/23/43 dtd.08.02.16	99750/-	Yes	Yes	No	No	No	TC to be done	15/294
29	Hydraulic Hose required for BCM 374 Machine during IOH Make:- PARKER, AEROQUIP, SUPERSEAL	BPL/W/TM/2015-16/23/43 dtd.08.02.16	135013/-	Yes	Yes	No	No	No	TC to be done	15/296
30	Transmission oil SAE-30 required for UTV machines. Make:- IOCL,BPCL,HPCL	BPL/W/TM/2015-16/23/43 dtd.08.02.16	138474/-	Yes	Yes	No	No	No	TC to be done	15/305
31	Tamping Arm required for Unimate machine. Part No.W37.1703. Make:- Plasser or equivalent.	BPL/W/TM/2015-16/23/43 dtd.08.02.16	89600/-	Yes	Yes	No	No	No	TC to be done	15/306
32	Air compressor req. MWM engine	15-16/175/168 dtd.08.03.16	77179	Yes	Yes	No	No	No	TC to be done	14/271
33	Hydraulic motor required for CSM	15-16/176/169 dtd.08.03.16	137025	Yes	Yes	No	No	No	TC to be done	15/307