

ANSWER TO FAC-95

SCHNEIDER ELECTRIC INFRASTRUCTURE LIMITED MAKE IOH REPLACEMENT KIT FOR SINGLE BOTTLE  
VCR TYPE 22CB CODE NO. 5510750

SR. NO.	PART NO.	DESCRIPTION	QTY IN SET	UNIT	REMARKS
✓	5510750	IOH REPLACEMENT KIT CONSIST OF :			
A	5510740	AOH REPLACEMENT KIT CONSISTING OF :	1	Kit	
1	5269760	- O RING FOR MAGNET VALVE ASSEMBLY	3	Nos	
2	5269860	- O RING FOR MAGNET VALVE ASSEMBLY	2	Nos	
3	5269500	- VALVE (FLUTED) FOR MAGNET VALVE	2	Nos	
4	5578080	- O RING FOR RELAY VALVE & REDUCER	2	Nos	
5	5578090	- O RING FOR RELAY VALVE ASSEMBLY	1	No	
6	5578100	- O RING FOR RELAY VALVE ASSEMBLY	1	No	
7	5578110	- O RING FOR RELAY VALVE ASSEMBLY	1	No	
8	5150020	- PTFE VALVE DISCS FOR RELAY VALVE	2	Nos	
9	5540060	- SPECIAL WASHER FOR MAIN PISTON	1	No	
10	5510163	- SEALING WASHER FOR BOTTOM COVER	8	Nos	
11	5510164	- RETAINING RING FOR BOTTOM COVER	8	Nos	
12	5110600	- REPAIR KIT FOR AIR FILTER CONSISTING OF	1	Kit	
		a) O' RING - 1 No			
		b) GASKET - 2 Nos.			
		c) STUD - 1 No.			
13	5110422	REPAIR KIT FOR PRESSURE REGULATOR CONSISTING OF ONE NO EACH, DIAPHRAGM ASSEMBLY, SEEP RING, VALVE, VALVE SEAT, GASKET SEAT & VALVE SPRING	1	Kit	
14	5510280	WASHER FOR DANJO COUPLING	3	Nos.	
15	5290340	PVC CHANNEL FOR GIMOTA CONN. PLATE	03	Mtrs.	
B		BALANCE IOH KIT :			
16	5380550	GROMMET FOR BASE PLATE	1	No	
17	5510390	O' RING (BETWEEN FLANGE)	1	No	
18	5510450	SELON WASHER (FOR PLUG OF CYLINDER)	1	No	
19	5510310	GASKET FOR BASE PLATE	1	No	
20	5510162	SEALING STRIP FOR BOTTOM COVER	23	Mt	
21	5540030	DAMPER ASSEMBLY FOR CYLINDER	1	No.	
22	5570050	PISTON SEAL RING FOR RELAY VALVE PISTON	1	No.	
23	5540023	PISTON SEAL RING FOR MAIN PISTON	1	No.	
24	5510490	FILTER ELEMENT	1	No.	
25	53901001	MOLECULAR SIEVES FOR AIR DRYER	4	kg	
26	5350000	SURGE SUPPRESSOR FOR MAGNET VALVE ASSEMBLY	1	No.	
27	5150010	POPPET VALVE FOR RELAY VALVE	1	No.	
28	5203400	AUXILIARY CONTACT UNIT (8-WAY)	1	No.	

On  
AEEETlow/ke/wor

A Kumar

अमित कुमार

Amit Kumar

उप मुख्य सामग्री प्रबंधक/विद्युत

Chief Materials Manager/Electrical