

Office of the DyCE(TM)/BPL
Status of released of Security Deposit

Nov,2018

Sr.No.	Name of work	Name of firm	Date of physical completion of work	Date of letter sent to Finance for release	Date of release Tantative	Remarks
1	Seal ring required for Rail Wheel of T-28 machine.Part no. WRI-215 Make-Ameca or Equivalent	M/s Sunbeam Industrial Products.	30.12.17	01.11.18	
2	Throttle valve required for Track Machines.Part no. WM388 Make-Plasser or Equivalent.	M/s Sunbeam Industrial Products.	10.02.18	01.11.18	
3	Transmission oil SAE-30 required for UTV machines working in WCR.Part no. SAE-30 Make IOCL/BPCL/HRCL.	M/s Bhopal Machinery Company	10.08.18	01.11.18	
4	Spares required for repairing of bosch self-starter 24 Volt duetz engine SL no. 0462 & 078414 supply and fitting for BCM machine. Make- Bosch.	M/s Sunita Diesels	06.08.16	09.11.18	
5	Supplying and fixing of spares required for complete rewiring of UTV-006 machine working in WCR.	M/s Hi-Tron Engineers	30.07.18	09.11.18	
6	Wheel support cylinder required for Track Machine.Make-Plasser Or Equivalent.	M/s Riddhi Tecnologies	09.05.17	09.11.18	
7	Tamping Arm required for Unimate machine.Make-Plasser or Equivalent.	M/s Riddhi Tecnologies	11.10.16	09.11.18	
8	Floor mate required for track machine.Part no. 600x600x10mm Harness 86±5,Make-Indegenous	M/s Sunita Diesels	24.02.17	14.11.18	

Office of the DyCE(TM)/BPL
Status of released of Security Deposit

Nov,2018

Sr.No.	Name of work	Name of firm	Date of physical completion of work	Date of letter sent to Finance for release	Date of release Tantative	Remarks
9	Bearing required for FRM machines.Part no.22212 Make-SKF,FAG	M/s Commercial Enterprises	13.04.18	15.11.18	
10	Spares required for UNI-4S-8410 machine.Make-Plasser	M/s Agromach Spares Corporation	15.05.18	15.11.18	
11	Valve required for T-Exp machines working in WCR.Part no.HY6RSB-B Make-Plasser	M/s Agromach Spares Corporation	17.12.17	15.11.18	
12	Spares required for Duetz Engine of BCM Machine. Working in WCR. Make-Duetz.	M/s South Calcutta Diesels Pvt.Ltd.	27.04.18	26.11.18	
13	Supply of material on normal purchase	M/s Multitech Engineers & Consultant	17.09.17	27.11.18	
14	Turbo charger required for Cummins engine NTA855 LBC Part No.3801918. Make-Cummins Holset	M/s Sunita Diesels	01.09.18	30.11.18	
15	Spares required for supply fixing and attention of NTA-855 big cam Engine of ATRT machine.Make-Cummins or EQ.	M/s Sunita Diesels	11.07.18	30.11.18	