


LH DRAWN/RH OPPOSITE



SECTION 'A-A'



ITEM NO 1

- NOTE:
1. MATERIALS GIVEN TO BE SAME TO GIVE AT 47%
  2. QUALITY SHALL BE PROVED AND CHECKED BY THE QUALITY CONTROL
  3. GOOD QUALITY MATERIALS AND FINISH SHALL BE USED THROUGHOUT
  4. FINISH SHOULD BE EVEN AND BOUNDED AND COLOR OF FINISH
  5. FINISH SHOULD BE WITH THE COLOR OF ALUMINUM
  6. FINISH SHOULD BE WITH THE COLOR OF ALUMINUM
  7. FINISH SHOULD BE WITH THE COLOR OF ALUMINUM
  8. FINISH SHOULD BE WITH THE COLOR OF ALUMINUM
  9. FINISH SHOULD BE WITH THE COLOR OF ALUMINUM

NO.	DATE	DESCRIPTION	BY	CHKD	SCALE	PROJECT
1	23.06.2010	NOTE NO 7 DELETED AND 8 AND 9 ADDED			1:1	LONG SEAT COMPLETE FOR SLR/GS BEWL COACH

NO.	DESCRIPTION	QTY	UNIT	REF
1	ALUMINUM 1800 X 545 X 1.5	1	NO	1
2	WOODEN PARTS 1800 X 545 X 1.5	1	NO	1
3	GLASS 1800 X 545 X 1.5	1	NO	1
4	GLASS 1800 X 545 X 1.5	1	NO	1
5	GLASS 1800 X 545 X 1.5	1	NO	1
6	GLASS 1800 X 545 X 1.5	1	NO	1
7	GLASS 1800 X 545 X 1.5	1	NO	1
8	GLASS 1800 X 545 X 1.5	1	NO	1
9	GLASS 1800 X 545 X 1.5	1	NO	1

LONG SEAT COMPLETE FOR SLR/GS BEWL COACH

WEST CENTRAL RAILWAY COACH REHABILITATION WORKSHOP NISHAT PURA BHOPAL

DRG. NO. C.RW/SK847