

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ER03151


Type : WGSCZAC

Built Year : 2003

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
Yellow	Headstock Beam	2	100%	Dark Green	Centre Stiffner for Headstock	4	100%	Light Green	Floor Stiffner for Headstock	4	100%
Dark Blue	Aux. Head stock	4	100%	Pink	Sole Bar	5	31%	Light Blue	Draft Gear Bracket	2	100%
Yellow	Trough floor	2	29%	Light Blue	Centre plate	2	100%		SoleBar Stiffner	4	100%
	Bottom Wall Part	5	31%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	0	0%		Window Bar	0	0%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 4, WEST : 0 Other End - EAST : 2, WEST : 0
Start Date : 17-Apr-2018, Completion Date : 28-Apr-2018, Net Repair Days : 11, Total Man Hours : 1584

MAYANK PRAJAPATI - JE	R KU KHARE - SSE	T K PANJA - SSE	A.R.R. KURUP - SSE In-charge	Verified By:QU-Incharge
-----------------------	------------------	-----------------	------------------------------	-------------------------

Coach Rehabilitation Workshop, WC Railway, Bhopal

(An IMS and ISO 50001 Certified Workshop)
Final Inspection Sheet - Details of Corrosion Repair

Coach No. :ER05406


Type : GS

Built Year : 2005

Make : ICF

Form No. F/BR/ICF/002

Valid From: 02/04/2015



Rotary Side

Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%	Color	Particulars	Qty	Per%
	Headstock Beam	2	100%		Centre Stiffner for Headstock	4	100%		Floor Stiffner for Headstock	4	100%
	Aux. Head stock	4	100%		Sole Bar	16	100%		Draft Gear Bracket	2	100%
	Trough floor	2	29%		Centre plate	2	100%		SoleBar Stiffner	6	100%
	Bottom Wall Part	16	100%		Body panel/patch		100%		Door Top/Roof Patch		0%
	Window Module		0%		Window Sill	40	100%		Window Bar	60	34%
	Seat pillar/lav. Partition		100%		UIC end construction		0%				

End Drooping: Rotary End - EAST : 2, WEST : -3 Other End - EAST : -8, WEST : -2
Start Date : 28-Mar-2018, Completion Date : 10-Apr-2018, Net Repair Days : 12, Total Man Hours : 1826

S K SHARMA - SSE	PANKAJ KU SINGH - JE	ARUN SINGH - SSE	A.R.R. KURUP - SSE In-charge	Verified By:QU-Incharge
------------------	----------------------	------------------	------------------------------	-------------------------